

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	8	2	8	2	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.02.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Narayanapet	Chinnajatram	33kv	Narayanapet	02.55	07.45	04.50	EL/OL	33KV Pole damaged and Isolator open Nidugurthy SS	Chinnajatram	-
1	NLG	Wadapally	A.D.Pally	33kv	Miryalaguda	13.50	23.05	09.15	OL	Jumper cut 4 Locations Points	A.D.Pally	-

TSSPDCL - LMRC / Corporate office

Date: 29.02.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Amistapur Town	11kv	Jadcherla	09.15	10.05	00.50		Bird Died on The 11Kv Line Near MRO Office Side Bhoothpur.	-
1	NLG	Marriguda	Y.G.Pally	11kv	Devarakonda	09.00	11.44	02.44	E/L & O/L	11 Line Cut	-
2		Gudipally	Gudipally	11kv	Devarakonda	16.48	17.45	00.57	E/L	11 Kv Jumper Cutt	-
3		Penpahad	S.R.Palem	11kv	Suryapet	07.30	09.50	02.20	E/L	Bird Fallen on the Line	-
4		Nelamarry	V.R.Puram	11kv	Huzurnagar	08.00	10.00	02.00	EL	Due to 11Kv Jumper Cutted	-
5		Panthangi	Panthangi Indl	11kv	Choutuppal	10.40	12.22	01.42	EL/OL	11kv Insulator Failed Near Aregudem Village	-
6		Puligilla	Puligilla	11kv	Choutuppal	02.45	08.30	05.45	EL/OL	11 kv Insulator failed at SS-20 Near Puligilla village	-
1	HYD N	Clock Tower	Natraj	11kv	Clock Tower	14.30	15.40	01.10	All Indication	3way RMU Cable fault at Kamath Hotel	