

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		5		5		5			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>16</b>	<b>0</b>	<b>16</b>	<b>0</b>	<b>16</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 02.01.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
<b>Nil</b>												

TSSPDCL - LMRC / Corporate office

Date: 02.01.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Annasagar	Tatikonda	11KV	Jadcherla	07.38	11.11	03.33		11KV Insulator Failed near Tatikonda	-
1	NLG	Thatipamula	Sri Ram Thanda	11KV	Suryapet	08.00	10.35	02.35	EL	Insulator failed	-
2		Mattampally	Allipuram	11KV	Huzurnagar	19.30	21.30	02.00	EL	11 KV Jumper cut	-
3		Dirsincherla	Narsaigudem	11KV	Huzurnagar	06.50	08.10	01.20	EL	11 kv line snapped	-
1	SDPT	Guruvannapet	Guruvannapet	11KV	Husnabad	00.00	07.30	07.30		BD,Conductor snapped	
2		Katkur	Katkur Rural	11KV	Husnabad	07.30	10.30	03.00		BD,Conductor snapped	
1	RR E	IICT	Snehapuri	11KV	Habsiguda	17.55	19.15	01.20		Tree fallen on 11kv line at Streete no 14 Nagarjuna nagar	-
2		Uppal	Raghavendra colony	11KV	Habsiguda	18.10	19.05	00.55		Tree fallen on 11kv line at Raghavendra nagar	-
3		AS Rao Nagar	Maruthi Nagar	11KV	SKP	05.17	06.06	00.49		11Kv Insulator failed at Office front side (Artisan Ramesh/Raju)	-
4		Moula-Ali	Spectra	11KV	SKP	10.15	10.55	00.40		BEML Compony SM Lab CTPT Problem IDA Moula-Ai (Artisan/Raju)	-
5		Anandbagh	Vinayak Nagar	11KV	SKP	17.55	19.03	01.08		Ground Petrolling done No Visible fault found due to Heavy Rain	-
1	HYD N	Yousufguda	Hylam Colony	11KV	Banjarahills	17.02	18.20	01.18	EL,OL-Rph	HT Jumper cut at Jalagam Vengal Rao House	-
2		Gymkhana	Ranibagh	11KV	Bowenpally	17.17	18.26	01.09	EL	Tree branches fallen on lines at Classic Garden	-
3		Nehru Nagar	LIC Colony	11KV	Bowenpally	17.38	20.43	03.05	EL	Tree branches fallen on lines at J.B.S Nala	-
4		Monda Market	Palika Bazar	11KV	Sec-Bad	18.05	19.30	01.25	EL	HT Service fault at Jain Mandir	-
5		Gymkhana	Tadbun Temple	11KV	Bowenpally	17.17	21.30	04.13	A.R. tripped	Jumper snapped at Modi Moters	-