

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		2		2		2			
3	MDK	107	933		1		1		1			
4	SDPT			1		1		1				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	4	2	4	2	4	0	0	
	Grand Total	1082	6468	2	9	2	9	2	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33kv	Narayanapet	18.50	19.30	00.40	E/L	Line Patrolling ,No Visible fault	Krishna	-
1	SDPT	Gajwel	Hamdhipur	33kv	Gajwel	02.30	07.25	04.55		B/D due to Insulator Failed	Hamdhipur	-

TSSPDCL - LMRC / Corporate office

Date: 05.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Thirumalapur	Thirumalapur	11kv	Jadcherla	08.15	12.12	03.57		11KV Wire cut near Thirumalapur	-
1	NLG	Chamapur	Chamapur	11kv	Bhongir	09.30	12.20	02.50	EL	11 kv Insulator failed at SS-1 Near Chamapur Village.	-
2		Yennaram	Kakkireni	11kv	Choutuppal	22.30	08.25	09.55	EL	11 kv Disc Failed Near Kakkireni Village.	-
1	MDK	Bollaram-I	Kythana	11kv	Patancheru	02.30	05.00	02.30		B/D due to Conductor snapped	-
1	RR E	RGK	Nissa	11kv	Sainikpuri	13.20	14.09	00.49		AB Switch Open Nissa Campus T/F Problem (L Insp Venkata Swamy)	-
2		Vasanthapuri	Sairam	11kv	Sainikpuri	16.45	18.00	01.15		UG Cable fail at near Sai Ram Theater (AE/OP)	-
3		Uppal	Bank colony	11kv	Habsiguda	21.40	23.00	01.20		11KV Pin Insulator Top Clamp Failed At KV 2	-
4		Rampally Dayara	Vanneguda AGL	11kv	Keesara	10.05	10.45	00.40		11KV Vanneguda AGL feeder breaker fault at SS Yard & Load added to Vanneguda Industrial feeder	-
1	HYD N	Seethaphalmandi	Medi Bavi	11kv	Secunderabad	16.56	18.25	01.29	EL,OL	Breaker spring charge problem at SS & HT Jumper cut at Booth Banglow	Arranged B/F on 11KV Seethaphal Mandi fdr