

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044	1	1	1	1	1	1			
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	1	5	0	0	
	Grand Total	1082	6468	2	6	2	6	2	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.01.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Gummadidala	GPSS-II	33KV	Patancheru	10.36	12.35	01.59		B/D Due to Conductor Snapped	Gummadidala	No
1	HYD S	132KV M.D.Pally	Devibagh	33KV	Malakpet	11.10	11.20	00.10	EL,OL-Yph	Under Breakdown	132KV M.D.Pally	Loads transferred onto 132KV Imlibun SS via 33KV Petlaburz SS

TSSPDCL - LMRC / Corporate office

Date: 09.01.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marikal	Chakalpally	11KV	Jadcherla	04.35	11.00	06.25		11KV Jumper Cut Near Mogulapally (V)	-
1	NLG	Eduloor	Kurumarthy	11KV	Nalgonda	07.20	10.40	03.20	E/L	11KV Jumper Cut	-
2		Thungathurthy	Ganugubanda	11KV	Suryapet	05.50	09.10	03.20	E/L	Disc Flashover	-
3		Raghunadapalem	Nakkalagudem	11KV	Huzurnagar	09.40	10.50	01.10	OL	Due to 11Kv Jumper Cutted	-
4		Mattapally	Mattapally	11KV	Huzurnagar	04.30	07.30	03.00	EL	Due to 11Kv Jumper Cutted	-
1	HYD N	Jubilee Hills	Art Gallery	11KV	Banjarahills	19.05	20.15	01.10	EL	Cable fault	Arranged B/F on 11KV Ohri's feeder