

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	4	1	4	1	4	0	0	
	Grand Total	1082	6468	1	6	1	6	1	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.01.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Gudeballore	33KV	Narayanpet	00.45	02.15	01.30	E/L	Insulator Failed & Pin Binding work	Makthal	Alternate Supply Arranged From 33KV Krishna Feeder at 2:15Hrs

TSSPDCL - LMRC / Corporate office

Date: 30.01.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Pittampally	11KV	Nalgonda	14.00	17.00	03.00	EL	11KV Jumper cut	-
2		B.Chandupatla	Thimmapuram	11KV	Suryapet	04.15	07.10	02.55	E/L	Disc Flasover	-
3		Palakeedu	Palakeedu-T	11KV	Huzurnagar	14.00	16.00	02.00	EL	Due to 11Kv wire cutted	-
4		Munagala	Bharakathgudem	11KV	Huzurnagar	03.35	06.35	03.00	EL	Due to 11Kv line snapped	-
1	RR S	ESCI	Lumbini Park	11KV	Kondapur	10.34	11.49	01.15	BD	11kv Line cut at Prestain mall, Lumbini Park	-
1	RR N	Jeedimetla-III	Back Lighty Hylam	11KV	Jeedimetla	15.35	18.00	02.25	EL/OL	11kv line AB CableEndkit Failure at New Laxmi Tifin Center, Phase-V road	-