

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT			2	14	2	14	2	14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	23	2	23	2	23	0	0	
	Grand Total	1082	6468	3	24	3	24	3	24	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Mustyala	Cherial	33KV	Husnabad	14.40	17.30	02.50		Tree branch fall on 33KV line Dhommata (V)		-
2		Palamakula	Gonepally	33KV	Siddipet	00.00	06.30	06.30		Insulater falure		-
1	RR N	132KV Malkaram	33KV Shameerpet	33KV	Medchal	00.00	01.55	01.55	BD	No Fault		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 06.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marrikal	Malkapur	11KV	Jadcherla	00.00	08.20	08.20		11KV Jumper cut near Thangallapally	-
2		Karkonda	Rudraram	11KV	Jadcherla	00.00	10.08	10.08		11KV Disk Fail near Rudraram	-
3		Pedda Revally	Bodagutta	11KV	Jadcherla	01.00	11.00	10.00		11KV Disk Fail near Jagya thanda	-
1	NLG	Velugupally	Keshavapuram	11KV	Suryapet	02.00	07.45	05.45	E/L	Insulator flashover	-
2		Durajpally	Khasimpeta	11KV	Suryapet	03.30	07.00	03.30	E/L	Jumper cut	-
3		B.Chandupatla	V.K Pahad	11KV	Suryapet	04.30	08.30	04.00	E/L	Disc failed	-
4		Dilchinchera	Narsaigudem	11KV	Huzurnagar	07.00	09.30	02.30	E/L	11KV Line snapped	-
5		Eduloor	Kurumarthy	11KV	Nalgonda	07.00	08.40	01.40	E/L	HT/LT Line milting	-
6		Ch.Laxmapur	Ch.Laxmapur	11KV	Bhongir	06.21	08.05	01.44	E/L	11 kv Line snapped at Bagaru well near Gopalapuram village	-
1	SDPT	Husnabad	Malapally	11KV	Husnabad	04.45	07.30	02.45		Heavy gale and wind	-
2		Thotapally	Thotapally rural	11KV	Husnabad	00.00	08.45	08.45		Line cut(3-ph)	-
3			Industrial	11KV	Husnabad	00.00	09.05	09.05		Heavy gale and wind(3-ph)	-
4		Rebharthi	Gagillapur	11KV	Husnabad	12.30	14.40	02.10		Heavy gale and wind	-
5		Mittapally	Yellupally	11KV	Siddipet	00.00	06.15	06.15		B/D-Disk fail now rectified	-
6		Kammarlapally	Kothapally	11KV	Siddipet	07.15	09.57	02.42		B/D-Tree bunches fallen on 11KV line now rectified	-
7		Peddakodur	Peddakodur	11KV	Siddipet	00.00	10.00	10.00		B/D-11KV disk fail now rectified	-
8		Ragothampally	Gosanpally	11KV	Siddipet	10.10	11.49	01.39		B/D-Tree bunches fallen on 11KV line now rectified	-
9		Jangapally	Jangapally	11KV	Siddipet	00.00	10.25	10.25		B/D-Disk fail now rectified	-
10		Mirdoddi	Andhe	11KV	Siddipet	06.00	13.45	07.45		B/D-Disk fail now rectified	-
11		Bejgama	Bejgama feeder (LC .No.7363 Praveen Reddy LM)	11KV	Gajwel	05.25	11.30	06.05		Disk fail	-
12		Kondapaka ss	Nacharam AGL LC.No.24311 Ilaiah LM)	11KV	Gajwel	03.30	10.30	07.00		Disk fail	-
13		Marpadaga SS	Nagireddy pally AGL LC.No.28197 Rahim JLM	11KV	Gajwel	01.30	08.50	07.20		Disk fail	-
14		Doulthabad SS	Lingareddy pally LC.No.1874 Dubbaiah LM	11KV	Gajwel	07:03	08:10	01.07		Insulater fail	-
1	RR N	Kompally	Kompally	11KV	Medchal	01.00	01.35	00.35	BD	11KV AB Cable sparked at Municipal Office	-