

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		5		5		5			
	Total	606	3055	1	9	1	9	1	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		3		3		3			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	11	2	11	2	11	0	0	
	Grand Total	1082	6468	3	20	3	20	3	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.07.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Shadnagar	Maamidipally	33KV	Shadnagar	18.40	20.25	01.45	O/L	Y Phase line insulator replacement at 220KV SS Shadnagar	Maamidipally	No
1	MDK	Jogipet	Laxmi sagar	33KV	Jogipet	20:00	21:30	1:30		Bus isolator failed at 132KV SS	Laxmi sagar	No
1	RR N	132KV Medchal	Steel Mills	33KV	Medchal	6:24	12:30	6:06		Bus Section -II for Connecting flash jumper cut and replaced in SS	Steel Mills	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marikal	Malkapur	11KV	Jadcherla	20.00	08.00	12.00		11 KV Wire cut near marikal (V)	No
1	NLG	Yerkaram	Das thanda	11KV	Suryapet	2:30	6:40	4:10	E/L	11KV Insulator flashover	No
2		Shantinagar	Shantinagar	11KV	Huzurnagar	13.30	15.15	01.45	E/L	11KV Line snapped	No
3		Malkapur	Malkapur Agl	11KV	Choutuppall	07.30	09.20	01.50	EL/OL	11KV Line snapped at indoreya Company near Malkapur village	No
1	MDK	Pati	Pati	11KV	Patancheru	13:40	14:10	0:30		Due to disc failed	No
2		Pati	Shalimar	11KV	Patancheru	19.10	20.40	01.30		Due to tree branches fallen on the line	No
1	SDPT	Bejagama	Jaligama	11KV	Siddipet	7:12	10:34	3:22		Copper patti failed	No
2		Pregnapur	Gundannapally Agl	11KV	Siddipet	08.22	09.22	01.00		Tree fallen on the line	No
3		Markook	Bavandapur Agl	11KV	Siddipet	10:20	12:00	01.40		11KV Line cut	No
4		Raipole	Chowderpally	11KV	Siddipet	17:30	19:44	2:12		11KV Line has cut and 2 Pleaces in Insulator failed	No
5		Godugupally	Godugupally	11KV	Husnabad	20:15	23.45	03.30		Tree fallen on the line	No
1	RR N	Kompally	Jaibheri	11KV	Medchal	19:12	20:00	0:48		11KV Line AB switch Opened at Nuziveed Seeds (No fault)	No
2		Kompally	Dholari Dhani	11KV	Medchal	19.13	20.20	01.07		11KV Line AB Switch Opened at Chandra Reddy Garden	No
1	RR E	Mallapur 2	Narsimha nagar	11KV	Habsiguda	11:40	12:30	0:50		Bird fallen on the 11kv line at Balaji appt	No
2		Peerzathiguda	Uppal hills	11KV	Keesara	15.35	16.20	00.45		Tree fallen on the 11kv line cut at Laxmi nagar	No
1	HYD N	New Bowenpally	Chandana Hospital	11KV	VI	18.55	21.20	02.25	EL,OL	HT conductor snapped at Bhavana Colony	No
1	HYD C	Asif Nagar	Mehdipatnam Cable	11KV	VII	14.05	15.28	01.23	EL,OL	Kept off faulty DTR at Mehdipatnam	No
2		Nizam College	Brand Factory	11KV	I	15.28	16.54	01.26	EL	Disc Insulator flash over at Himayath Nagar	No
3		Chilkaiguda	44 Bus Stop	11KV	II	16.05	17.40	01.35	EL,OL	Tree branches fallen on lines at 44 Bus Stop	Arranged B/F on 11KV Parsigutta fdr
4		Mothi Mahal	M.D.Lines	11KV	VII	16:22	17:44	1:22	EL,OL-Yph	No Visible Fault	Arranged B/F on 11KV Military Hospital fdr