

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		5		5		5			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		3		3		3			
3	MDK	107	933		1		1		1			
4	SDPT			2	8	2	8	2	8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	2	19	2	19	2	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Angadikistapur	Jagadevpur	33KV	Gajwel	14.08	15.31	01.23		BD (Line Problem)		-
2		Gajwel	KDA	33KV	Gajwel	01.30	04.30	03.00		BD Iso lighting arrest blasting		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 09.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Amistapur	11KV	Jadcherla	12.40	15.30	02.50		Tree Fallen On The 11KV Line Near Amistapur(V)	-
1	NLG	Repala	Repala	11KV	Huzurnagar	06.10	08.00	01.50	EL	11 KV LINE SNAPPED	-
2		Pamukunta	Singaram	11KV	Bhongir	00.00	08.30	08.30	EL	11 kv line snapped at Durgamma temple near Singaram village.	-
3		Chamapur	Singaram	11KV	Bhongir	00.00	08.00	08.00	EL	11kv Insulator Failed near Yasa Yadhireddy Well	-
1	MDK	Gummadidala	Agrobell	11KV	Patancheru	05.50	08.50	03.00		BD Due to CT/PT Problem	-
1	SDPT	Ankshapur	Nagarajupally	11KV	Siddipet	19.52	21.50	01.58		BD Tree Branches fallen on 11 KV	-
2		Raghavapur	Raorukula	11KV	Siddipet	17.45	18.55	01.10		Bird Fallen on 11 KV Line	-
3		Dharmajipet	Yegonda Swamy	11KV	Siddipet	00.00	03.00	03.00		BD Tree Branches fallen on 11 KV	-
4		Jagdevpur SS	Dowlapur AGL LC.No.5575 (Kumar LM)	11KV	Gajwel	10:01	16:40	6:39		Jumper Cut	-
5		Markook SS	Bhavandapur AGL Feeder Lc.No.11730 (Dhrshan LM)	11KV	Gajwel	06:25	08:30	01.55		Disk fail	-
6		Markook SS	Markook AGL Feeder Lc.No.11731 (Dhrshan LM)	11KV	Gajwel	7:33	8:30	01.03		11line Line has fallen on other 11 KV Line	-
7		Pandilla	Pandilla Rural	11KV	Husnabad	00.00	08.10	08.10		BD Tree Branches fallen on 11 KV	-
8		Pandilla	Kuchanpally	11KV	Husnabad	05.20	08.20	03.00		BD Tree Branches fallen on 11 KV	-
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	12.15	13.40	01.25	BD	Bird fallen on the 11KV Line at VRL Company	-
1	HYD N	New Bowenpally	Reliance Villa	11KV	Bowenpally	09.37	10.52	01.15	EL,OL	Cable End Kit failed at Tirumala Hills	-
1	HYD S	Womens College	V.P.Ground	11KV	Begumbazar	20.22	21.49	01.27	EL	Cable fault (2Nos. DTR's kept off)	Arranged B/F on 11KV Rang Mahal fdr
2		Malakpet Block	C-Quarters	11KV	Asmangadh	20.53	22.01	01.08	EL,OL	Tree branches fallen on lines at C-Quarters	-
1	HYD C	S.D.Hospital	Ahmed Nagar Cable	11KV	Mehdipatanam	00.40	02.27	01.47	EL	Cable fault at Military Area	Arranged B/F on 11KV Military fdr
2		Chilalguda	Bholakpur	11KV	Saifabad	18.05	19.05	01.00	EL,OL-Rph	Pin Insulator flash over at Kawadiguda	-