

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		9		9		9			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT			2	12	2	12	2	12			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	22	6	22	6	22	0	0	
	Grand Total	1082	6468	6	27	6	27	6	27	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Nandinne	33KV	Gadwal	07.40	10.42	03.02	O/L	Jumper Cut Near Chengonipally(V)		-
2		Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	11.45	13.30	01.45	E/L	Insulator Damaged at Desi Itikyala(V)		-
1	MDK	Gummadidala	AFA	33KV	Patancheru	07.45	11.35	03.50		BD due to Jumper cut		-
2		Gummadidala	GPSS-1	33KV	Patancheru	18.52	20.45	01.53		BD due to Insulator failed		-
1	SDPT	Thunkibollaram	Wantimamidi	33KV	Gajwel	05.00	05.05	00.05		BD (cable kit Burn)		Alternate supply arranged from 132KV Markook - 132KV Thunkibollaram at 05.05 hrs
2		Shanigaram	Chalimeda	33KV	Husnabad	19.00	20.50	01.50		BD (Pole Bended)		-

Circle-wise 11KV Breakdowns

Date: 12.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Yacharam	Annaram	11KV	Miryalguda	15.40	19.00	03.20	E/L	11Kv Disc fail near SS	-
2		Kasarabadha	Express feeder	11KV	Suryapet	15.25	17.00	01.35	E/L	11Kv Insulator failed	-
3		Patharlapahad	Istalapuram	11KV	Suryapet	04.00	07.28	03.28	E/L	11Kv Jumper cut	-
4		Dirsincherla	Narsaigudem	11KV	Huzurnagar	05.00	06.45	01.45	E/L	11kv line snapped	-
5		Ananthagiri	V R Puram	11KV	Huzurnagar	06.25	08.00	01.35	E/L	11Kv Jumper cut	-
6		MT.Pally	Dharamaram	11KV	Bhongir	06.00	07.25	01.25	EL/OL	11kv Line Snapped near Karshal Gaddathnda	-
7		MT.Pally	Vaslamarri	11KV	Bhongir	06.00	08.15	02.15	EL/OL	11kv Line Snapped near ZPHS School Vasalamarri	-
8		Bondugula	Bondugula	11KV	Bhongir	05.40	12.00	06.20	EL/OL	11kv Insultor Failed near Bondugula (V)	-
9		Laxmapuram	Thummalagudem	11KV	Choutuppal	05.45	08.45	03.00	EL/OL	11kv Insultor Failed near Thummalgudem (V)	-
1	MDK	SOL	BMF	11KV	Patancheru	08.45	12.15	03.30		BD due to Jumper cut	-
1	SDPT	Markook SS	Sneha Industrial Feeder LC :11746	11KV	Gajwel	11.55	12.40	00.45		Insularet Fail	-
2		Markook SS	Sneha Industrial Feeder LC :11747	11KV	Gajwel	14.00	16.00	02.00		Tree Cutting	-
3		Gowraram SS	11 KV Mailaram Feeder LC: 40301	11KV	Gajwel	4:15	08.00	03.45		Poles Broken	-
4		Gowraram SS	Gowraram Town-I LC: 40302	11KV	Gajwel	05.10	08.15	03.05		Tree Branch Falllen	-
5		Thunki Khalas SS	Amberpet Feeder LC No. 26760	11KV	Gajwel	1:40	5:00	3:20		11KV Insulater Fail	-
6		Nemtoor SS	Nemttor Feeder LC 40261	11KV	Gajwel	04:45	10:00	5:15		Jumper Cut	-
7		Kokkonda SS	Noojiveedu Seeds Feeder	11KV	Gajwel	01.20	04.20	03.00		Heavy wind	-
8		Mubaraspur SS	Mubaraspur Feeder LC: 4164	11KV	Gajwel	01.46	08.20	06.34		Insulater failure	-
9		Dommata SS	Surampally Feeder LC: 344	11KV	Gajwel	12.10	16.00	02.50		DTR Fail	-
10		THOTAPALLY	THOTAPALLY	11KV	Husnabad	17.00	19.46	02.46		JUMPER CUT	-
11		Ponnala	Kistasagar agl	11KV	Siddipet	14.40	16.30	01.50		B/D insuleter fail LC no 19274	-
12		Chinnagundavelly	Chinnagundavelly agl	11KV	Siddipet	04.30	07.25	02.55		B/D Disk fail	-
1	RR N	Jagathgirigutta	Jagathgirigutta	11KV	Medchal	04.00	04.25	00.25	BD	11KV Cable endkit failed at Durga matha Temple	-
2		Kompally	Jaibheri	11KV	Medchal	05.29	06.40	01.11	BD	Lizard fallen on the 11KV Line at Krishnam Raju DTR,	-
3		Subhash Nagar	Suchitra	11KV	Medchal	14.55	15.35	00.40	BD	Tree fallen on the 11KV Line at Quthbullapur Road	-
4		Kistapur	Welset	11KV	Medchal	06.35	07.50	01.15	BD	Tree Fallen on 11KV Line at Srinath Company	-
1	HYD S	Falaknuma	Chatrinaka	11KV	Charminar	06.20	07.43	01.23	EL,OL	Snapped 2No. HT Lines at Gowlipura	-