

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	8	2	8	2	8			
2	NLG	144	988		2		2		2			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	10	3	10	3	10	0	0	
	Grand Total	1082	6468	3	12	3	12	3	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shanathinagar1	33KV	Gadwal	21.42	23.26	01.44	EL	Tree branches fallen on the line	Shanathinagar1	NO
2		Thirumalaipally	Wiliamkoda	33KV	Wanaparthi	22.20	22.40	00.20	EL	Feeder under patrolling	Wiliamkoda	Alternate Supply Arranged from 33KV Pebbair feeder
1	MDK	Sadasivpet	Kondapur	33KV	Sangareddy	11.00	15.00	04.00		B/D Due to Jumper Cut	Kondapur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 18.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Machanpally	Ramchendrapur	11KV	Mahabubnagar	15.15	17.25	02.10		11KV Disk failure at Ramchendrapur shivaru	-
2		Annasagar	Annasagar	11KV	Jadcherla	08.15	09.38	01.23		11 KV Insulator fail near Annasagar	-
3		Sarjakhpet	Thogapur	11KV	Narayanapet	07.35	09.38	02.03		Disc Fault	-
4		Pallerla	Parsapur	11KV	Narayanapet	16.16	19.00	02.44		Disc Fault	-
5		Vennached	Janampally	11KV	Narayanapet	13.49	14.10	00.21		Jumper cut	-
6		Kotakonda	Bommanpad	11KV	Narayanapet	07.48	09.30	01.42		11KV Line cut due to gail	-
7		Gotur	P.pahad	11KV	Narayanapet	06.00	10.00	04.00		Disc replacement on Rakonda 11 KV line.	-
8		Maganoor	Wadwat	11KV	Narayanapet	17.45	19.45	02.00		Jumper cut	-
1	NLG	T Giri	NB Thanda	11KV	Suryapet	03.00	06.58	03.58	E/L	Jumper cut	-
2		Nandanam	Anajipur	11KV	Bhongir	12.15	14.00	01.45	E/L	11kv Line Snapped	-
1	HYD C	Golconda	Risala Bazar	11KV	VII	02.17	03.41	01.24	EL,OL-Rph	Cable fault at SS	Arranged B/F on 11KV Zinci Bazar feeder
2		Toli Chowki	Hakeemsha	11KV	VII	16.15	17.25	01.10	EL	DTR Cable fault at Satya Colony	-----