

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		4		4		4			
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	9	0	9	0	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	6	1	6	1	6			
2	NLG	144	988		8		8		8			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	16	1	16	1	16	0	0	
	Grand Total	1082	6468	1	25	1	25	1	25	0	0	

TSSPDCL - LMRC / Corporate office

Date: 22.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Revally	33KV	Wanaparthi	15.40	20.15	04.35	E/L&O/L	33KV Jumper Replacement & Tree Cutting at Appaipally Oil Mill	Revally	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 22.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Tankar	Tankar	11KV	Mahabubnagar	11.55	14.00	02.05		11KV Jumper cut at Tankar vilage 1x15kv failure	-
2		Vennached	Janampally	11KV	Narayanapet	12.00	13.24	01.24		11 KV Insulator Failed Near Chinna Waghu	-
3		Gundumal	Gundumal Agl	11KV	Narayanapet	06.30	08.30	02.00		11 KV Disc damage and replacement	-
4		Dhanwada	Dhanwada Agl	11KV	Narayanapet	14.40	16.00	01.20		2 Insulator Damages on 11 kv line	-
5		Kosgi	Sampally	11KV	Narayanapet	08.10	09.03	00.53		Tree cutting work near sampally vilage	-
6		Maddur	Dorepally	11KV	Narayanapet	08.10	09.15	01.05		11KV Insulator damage	-
1	NLG	Kanagal	B.D.Pally	11KV	Nalgonda	23.40	09.00	09.20	E/L	11KV Jumper cut	-
2		Rajupeta	Rajupeta	11KV	Nalgonda	16.25	19.00	02.35	E/L	11KV Jumper cut	-
3		Malkapur	Malkapur Agl	11KV	Choutuppal	07.20	10.25	01.15	E/L	11kv Line Snapped	-
4		Malkapur	Thurampet Agl	11KV	Choutuppal	08.20	12.00	01.15	E/L	11kv Line Snapped	-
5		Jai kesaram	Indl	11KV	Choutuppal	12.00	01.26	01.26	E/L	11 kv Insulator failed	-
6		Juloor	Kapraipally	11KV	Choutuppal	06.55	08.10	01.15	E/L	11 kv Pole dammaged	-
7		Janpahad	Janpahad	11KV	Huzurnagar	08.10	09.20	01.20	E/L	11 KV JUMPER CUT	-
8		G.T Giri	G.T Giri	11KV	Suryapet	10.45	11.57	01.12	E/L	Conductor snapped	-
1	SDP	GAGILLAPUR	GAGILLAPUR AGL	11KV	Husnabad	00.00	08.00	08.00		JUMPER CUT	-
2		MADDUR	MADDUR AGL	11KV	Husnabad	13.25	16.20	02.55		INSULATOR FAILURE	-
1	RR S	Chanda Nagar	Engineers Enclave	11KV	Gachibowli	15.15	17.10	01.55	BD	Tree branches fallon on the 11KV line at Old PS.	-
2		Papireddy Colony	Papireddy Colony	11KV	Gachibowli	16.45	17.45	01.00	BD	11KV Disc failed at Papireddy Colony Cheruvu	-
3		Chanda Nagar	Market	11KV	Gachibowli	15.40	17.15	01.35	BD	Tree branches fallon on the 11KV line at Narayana College	-
4		Kaithalapur	Anjaneya Nagar	11KV	Kondapur	17.45	18.45	01.00	BD	11KV AB Cable failed at Kallu compound	-
1	RR N	ICICI	SP-I	11KV	Medchal	00.00	01.00	01.00		11KV Cable end kit failed at RMU-I	-
2		GP Pally	Apparel Park	11KV	Medchal	17.00	18.00	01.00		Tree fallen on the 11Kv Line at Stayon Company Backside	-
3		Bowrampet	Bowrampet vilage	11KV	Jeedimetla	17.25	18.20	00.55		11kv Post of insulator failure at Bowrampet, due to rain	-
1	RR E	Moula ali	Spectra	11KV	Sainikpuri	18.50	19.45	00.55		11Kv Insulator failed at Twakalu Engg Work (Artisian Kistopher)	-
1	HYD N	Chilkaiguda	Dandu Pentaiah	11KV	V	04.20	05.45	01.25	EL,OL-Rph	RMU Cable fault	Arranged B/F on 11KV MCH Park feeder