

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		4		4		4			
2	NLG	144	988		3		3		3			
3	MDK	107	933		1		1		1			
4	SDPT				9		9		9			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	17	0	17	0	17	0	0	
	Grand Total	1082	6468	0	28	0	28	0	28	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 25.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Town	11kv	Jadcherla	00.30	07.14	06.44		11Kv Disc Failure Near Amistapur(Vi).	-
2		Mothiganapur	Medigaddatanda	11kv	Jadcherla	05.50	12.20	06.30		Medigadda Tanda,Kurvagadda Tanda,Kuntaloppu Tanda.	-
3		Manthangoud	Katchwar	11kv	Narayanpet	12.42	13.02	00.20		Insulator failed	-
4		Manthangoud	Katchwar	11kv	Narayanpet	14.42	16.55	02.13		11KV line Cut	-
1	NLG	Maryala	Chowderpally	11kv	Bhongir	04.30	07.40	03.10	EL/OL	11 kv Line snapped at Hanunmanth reddy thota Chowderpally village	-
2		Golankonda	Golankonda	11kv	Bhongir	04.00	08.00	04.00	EL/OL	11 kv Insulator failed near Ammanabole village	-
3		Choutuppal	Lingojigudem	11kv	Choutuppal	04.30	08.00	03.30	EL/OL	100 KVA DTR Failed near Ankireddygudem village	-
1	MDK	Dundigal	DRF	11kv	Patancheru	16.20	18.50	02.30		BD due to Disk failed	-
1	SDPT	Thotapally	Thotapally	11kv	HUSNABAD	10.48	10.48	00.00		B D , DUE TO INSULATOR FAILURE	-
2		Gouravelly	Gouravelly Rural	11kv		03.36	02.24	13.12		B D , DUE TO JUMPER CUT	-
3		Komuravelly	Kadavergu	11kv		12.00	01.12	03.36		B D , DUE TO INSULATOR FAILURE	-
4		Komuravelly	Gouraipally	11kv		01.12	01.12	00.00		B D , DUE TO INSULATOR FAILURE	-
5		Guruvannapet	Posanpally	11kv		06.00	02.09	10.33		B D , DUE TO HEAVY RAIN	-
6		KODAKANDLA SS	KUKUNOORPALLY FEEDER(LC.NO.9514)	11kv		18.00	19.20	01.20		11KV INSULATOR FAILED	-
7	MARKOOK SS	MARKOOK AGL FEEDER(LC.NO.11775)BHASKAR CL	11kv	GAJWEL	08.10	09.50	01.40		TREE BRANCH WAS FALLEN	-	
8	DAMARAKUNTA SS	DAMARAKUNTA FEEDER(LC.NO.30835)	11kv		19.50	21.58	01.08		JUMPER CUT	-	
9	KONDAPAKA SS	INDUSTRAIL FEEDER(LC.NO.24313)	11kv		17.00	18.30	01.30		11KV INSULATOR FAILED	-	
1	RR N	Madinaguda	Reddy Labs	11kv	Kukatpally	15.40	20.10	04.30		11kv Cable Failure At Krushi Colony	-
2		Kompally	Dholari Dhani	11kv	Medchal	12.44	14.15	01.31		11KV AB Cable failed at Harshitha Hospital	-
3		Uddamarry	Yellaguda	11kv	Medchal	16.45	17.35	00.50		Tree fallen on the 11KV Line at Yellaguda Village	-
4		Laxmapur	Narayanapur	11kv	Medchal	17.05	19.50	02.45		11KV Line cut and Disc failed at Narayanapur Village	-
1	RR E	Mallapur	Noma	11kv	Habsiguda	03.45	04.45	01.00		11KV Polymer Disc failed at Sri Chaithanya School	-
2		Techpark	Haryanasteel	11kv	Habsiguda	20.13	21.47	01.34		11Kv Lightning Erectior Failed Near Manoj Industry & 11KV Ab switch Insulator failed at Liquar India company	-
3		Vasanthapuri	Raja Nagar	11kv	Habsiguda	15.35	17.35	02.00		11Kv Disk failed at PVN Colony (LM Anand)	-
1	HYD N	Tirumalagiri	Officers Colony	11kv	C-VI	16.16	17.30	01.14	EL	Conductor snapped at Kendriya Vidyalaya	-
2		Zamistanpur	MCH Park	11kv	V	15.34	17.25	01.51	EL-OL-Rph	DF Point Insulator failed at MCH Park	-
3		I.I.C.T	Deccan	11kv	V	17.36	18.55	01.19	EL	Tree branches on lines at Road No.14	-
4	Hyd C	Amberpet	Play Ground	11kv	II	16.45	18.35	01.50	EL	2no Pin Insulator flash over at Vani Photo Stuido & Kareena Functional Hall	-