

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933									
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	8	3	8	3	8	0	0	
	Grand Total	1082	6468	3	12	3	12	3	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Chinnamaroor	33KV	Wanaparthi	17.45	17.55	00.10	E/L	No Visible Fault	Chinnamaroor	Alternate Supply Arranged to 33KV Velgonda Feeder at 17:55Hrs
2		220/33KV SS Singotam	Kudikilla	33KV	Nagarkurnool	09.54	10.32	00.38		No Visible Fault	Kudikilla	-
1	NLG	Aitipamula	Kethepally	33KV	Nalgonda	07.06	11.44	04.38		33KV Jumper cut	Kethepally	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 26.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Chamapur	Singaram	11KV	Bhongir	06.00	09.50	03.50	EL	11 kv Line snapped	-
2		Mandollagudem	Nelapatla	11KV	Choutuppal	03.00	09.34	06.34	EL	100 KVA DTR Failed	-
1	SDP	Ponnal	Ponnal	11KV	Siddipet	07.40	09.30	01.50		B/D for Disk fail	-
2		Chittapur	Mothey	11KV	Siddipet	16.23	17.19	00.56		B/D for Insulator fail LC No.12559	-
3		ERRAVALLY	ERRAVALLY AGL (LC.NO:26337) LAXMAN.LM	11KV	Gajwel	12:30	14:45	02.15		LT LINE OPENED	-
4		DHAMARAKUNTA	DHAMARAKUNTA (LC.NO:30835) DHARSHANAM.LM	11KV	Gajwel	8:20	9:50	01.30		BREAK DOWN (Tree Fallen)	-
5		ADAVIMAZIDH	KUTHYAL (LC.NO:27419) MALLESHAM.LI	11KV	Gajwel	09.32	11.05	03.30		11 KV LINE CUT	-
6		GURRALASOPA	WADDEPALLY VILLAGE (LC.NO:2802) BIXAPATHI.JLM	11KV	Gajwel	8:25	10:55	02.30		CUPPER TOUCHED LT LINE	-
1	RR N	Aleap	Madhuranagar	11KV	Jeedimetla	00.20	01.30	01.10	EL/OL	11kv Jumper Cut touched Channel At Prgathinagar	-
2		Aleap	Pragathinagar	11KV	Jeedimetla	08.25	09.25	01.00	EL/OL	Tree Branches Fallen On The 11kv Line At Pt 799 Pragathinagar	-
1	RR E	Mallapur	Standed tiles	11KV	Habsiguda	19.10	19.40	00.30		line petroling done no falt found & Line AB Swith at SBI bank	-
1	HYD N	Bowenpally	Jaya Nagar	11KV	VI	04.20	05.30	01.10	EL,OL-Bph	Cable fault at Vittal Nagar (1No. DTR Kept Off)	-