

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	14	0	14	0	14	0	0	
	Grand Total	1082	6468	1	16	1	16	1	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.07.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYDC	132KV Nims	Lakeview	33KV	Hussainsagar	14:32	14:36	0:04	EL	Lighting arrestors failed and repaired	Lakeview PTR-2	Alternate supply arranged from 132kV Hussainsagar - 33KV Hussain sagar-2 at 14.36 hrs. regular feeder idle charged at 17.40 hrs.

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Golankonda	Golankonda	11KV	Bhongir	1:55	7:55	6:00	EL/OL	11KV Line snapped at Bheemagani Narsireddy well near Ammanabole (V)	No
2		Dirsincherla	Dirsincherla	11KV	Huzurnagar	15.00	16.20	01.20	E/L	11KV Line snapped	No
3		N Annaram	Lingala	11KV	Suryapet	06.00	09.18	03.18	E/L	11KV Insulator flashover	No
4		Narketpally	M.Yadavally	11KV	Nalgonda	08.40	09.20	00.40	E/L	AB Switch female cut	No
5		Rajupeta	Jonnalagaddagudem	11KV	Nalgonda	16.00	16.45	00.45	E/L	Movement fault	No
6		Eduloor	Kurumarthy	11KV	Nalgonda	12.00	12.40	00.40	E/L	11KV Jumper cut	No
7		Pottichelma	Chalaturthy	11KV	Miryalguda	10:00	11:50	1:50	E/L	11KV Line snapped	No
1	MDK	Sadasivapet Town	Town-III	11KV	Sangareddy	19:09	21:11	2:02		Disc failed	No
1	SDPT	Ensanpally	Ensanpally	11KV	Siddipet	20:15	21:30	1:15		B/D 100KVA DTR Off	No
2		Raghavapur	Peddalingareddypally	11KV	Siddipet	17.10	18.50	01.40		B/D AB Switch open	No
3		B V Pur	Bangla Venkatapur	11KV	Gajwel	15.40	17.28	01.29		Incoming supply failed	No
4		Vantimamidi	Industrial	11KV	Gajwel	06.32	09.15	03.30		Pole damaged	No
5		Dommat	Dommat	11KV	Gajwel	12.32	14.18	01.46		11KV Phase to phase	No
6		Gouravelly	Gubbadi	11KV	Husnabad	11:15	12:20	1:05		DTR Problem	No
1	RR N	Thumkunta	Thumkunta	11KV	Medchal	9:00	9:40	0:40		No visible fault	No
2		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	02.25	03.27	01.02		Tree fallen on the 11KV line at Shiva Shivani School	No