

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933		2		2		2			
4	SDPT			2	10	2	10	2	10			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>20</b>	<b>3</b>	<b>20</b>	<b>3</b>	<b>20</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>28</b>	<b>4</b>	<b>28</b>	<b>4</b>	<b>28</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 28.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Nalgonda	Pazzur	33KV	Nalgonda	14.00	16.50	02.50	EL	33 KV Jimper Cut		-
1	SDPT	Chandlapur	Kammalapally	33KV	Siddipet	09.29	10.23	00.54		Insuletar felure		
2		Chandlapur	Kammalapally	33KV	Siddipet	15.22	16.10	00.48		Insuletar felure		
1	RR N	132KV Medchal	33KV Keshavaram	33KV	Medchal	09.48	16.05	01.05		Tree removed on the 33KV Line at Medicity SS		-

## Circle-wise 11KV Breakdowns

Date: 28.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Bopparam	Bopparam	11KV	Suryapet	15.10	16.10	01.00	EL	Jumper cut	-
2		BNL Thanda	BNL Thanda	11KV	Huzurnagar	10.00	12.30	02.30	EL	11 KV LINE SNAPPED	-
3		Palem	Bopparam	11KV	Nalgonda	13.30	16.00	02.30	EL	11 KV Jumper Cut	-
4		Nakkalapally	Shapally	11KV	Nalgonda	14.20	15.47	01.27	EL	11 KV Jumper Cut	-
5		Narketpally	Mandra	11KV	Nalgonda	13.30	17.20	03.50	EL	Due to Heavu Rain	-
6		Narketpally	Express	11KV	Nalgonda	14.15	16.20	02.05	EL	11 KV Jumper Cut	-
7		Damarcherla	T.V.gudem	11KV	Miryalaguda	12.36	13.15	00.39	EL	11KV Jumper cut	-
8		Golnepally	Golnepally	11KV	Choutuppal	15.30	16.50	01.20	EL	63KVA DTR Insulator Filed Golneypally Village	-
1	MDK	Patancheru Town	Town Indl.	11KV	Patancheru	08.25	09.15	00.50		BD due to Insulator failed	-
2		Gummadidala	Bell Remedies	11KV	Patancheru	19.20	22.00	02.40		BD due to Insulator failed	-
1	SDPT	BEJJANKI	REGULAPALLY	11KV	Husnabad	02.24	12.00	09.36		B D , DUE TO TREE BRANCH FALLEN ON LINE	-
2		GANDIPALLY	RAMAVARAM X PRESS FEEDER	11KV	Husnabad	00.10	02.24	02.14		B D , DUE TO TREE BRANCH FALLEN ON LINE	-
3		Komuravelly	Kadavergu	11KV	Husnabad	07.12	12.00	04.48		B D , DUE TO DISK FAILURE	-
4		Komuravelly	Gouraipally	11KV	Husnabad	07.12	13.12	06.00		B D , DUE TO DISK FAILURE	-
5		Nagapuri	Gandikunta	11KV	Husnabad	04.48	07.12	02.24		B D , DUE TO HEAVY RAIN	-
6		KODAKANDLA	KUKNOOR PALLY (LC.NO:9523) KARNAKAR.LM	11KV	Gajwel	18.20	19.10	01.20		JUMPER OUT	-
7		BANDARAM	BANDARAM (LC.NO:38329) NARENDER .LI	11KV	Gajwel	17:20	18:30	1:10		BIRD FALLEN ON THE 11 KV LINE	-
8		MEDNIPUR	KUKNOOR PALLY (LC.NO:) RAVI.CL	11KV	Gajwel	14:52	16:30	1:40		TREE BRANCHES FALLEN ON LINE	-
9		MUBARASPUR	THIRUMALAPUR	11KV	Gajwel	18.40	23.59	4:19		3PH OFF ONLY RUNNING 1PH	-
10		ANAJPUR	ANAJIPUR (LC.NO:6201) NARSIMLU.CL	11KV	Gajwel	15:20	17:25	02.05		POLE DAMAZE	-
1	RR S	Mathrusri Nagar	Srila	11KV	Gachibowli	19.25	20.25	01.00	BD	Bird fallon on the 11KV Line and pin insulator failed near SS Back side	-
1	RR N	Somasila	Ramalayam	11KV	Kukatpally	15.22	16.26	01.04		11KV Endkit failure at Ramalayam temple	-
2		GP Pally	Neighbourhood	11KV	Medchal	09.25	10.10	00.45		11KV Conductor Snapped and replaced at Aparna Opp	-
1	RR E	Sainikpuri	Sainikpuri	11KV	Sainikpuri	16.25	17.25	01.00		Post of Insulator failed at Sainikpuri (AE)	-
2		Aushapur	NFC nagar	11KV	Keesara	16.40	18.10	01.30		2 11KV pole damaged at KV scholl opp	-
3		Aushapur	Ankushapur	11KV	Keesara	16.40	18.20	01.40		1 11kv pole damaged at Jagath swapana venchar	-
1	HYD N	Bansilalpet	Viceroy	11KV	Sec-Bad	03.00	04.20	01.20	EL	RMU fault at Budha Bhavan	-
2		Monda Market	Monda Market	11KV	Sec-Bad	12.01	13.55	01.54	EL,OL-Rph	HT Jumper cut at Monda Market	-