

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	8	0	8	0	8	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	12	0	12	0	12	0	0	
	Grand Total	1082	6468	0	20	0	20	0	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.07.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 29.07.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gotur	Rakonda	11kv	Narayanapet	07.00	07.50	00.50		11KV Insulator Damage	-
1	NLG	Chedella	Mukundapuram	11kv	Suryapet	14.00	17.20	03.20	EL	Insulator flashover	-
2		Gondiryala	Kothagudem	11kv	Huzurnagar	06.30	08.30	02.00	EL	11 KV JUMPER CUT	-
3		Cheruvugattu	Sherubavigudem	11kv	Nalgonda	04.30	07.00	02.30	EL	11 KV Jumper Cut	-
4		N.S.Batla	Gadibhigudem	11kv	Nalgonda	05.00	08.45	03.45	EL	11 KV Jumper Cut	-
5		Ishkilla	Kakkireni	11kv	Choutuppal	04.00	10.15	06.15	EL/OL	11KV Insulator Failed near Pole No 20	-
1	MDK	Jangapally	Jangapally	11kv	Siddipet	16.05	23.50	07.45		Tree branch has fallen	-
2		KOKONDA	KOTHUR & SINGANNAGUDA & NUGIVIDU (LC.NO:467) YADAGIRI. CL	11kv	Gaajwel	16.25	17.10	00.55		Tree branch has fallen	-
3		DOMMAT	SURAM PALLY (LC.NO:3310) SRINIVAS.ALM	11kv		18.26	19.26	00.58		BIRD FALLEN ON THE 11 KV LINE	-
4		Akkannapet	Pakilnayak Thanda	11kv	Husnabad	10.00	10.20	00.20		11KV Line cutting	-
5		Gandipally	Gandipally	11kv		00.00	07.00	07.00		3-Ph BD , 1-Ph ok	-
6		Komuravelly	Posanpally	11kv		07.30	10.30	03.00		3-Ph BD , 1-Ph ok	-
1	RR N	Prashanthi hills	Srinivasa colony	11kv	Kukatpally	18.30	20.08	01.38	BD	11 KV Disk, jumper cut at Abhigyna School	-
2		Medchal	Check post	11kv	Medchal	08.15	09.30	01.15	BD	CTPT failed at Twin Cities Company	-
1	RR E	Keesara	Vardhana	11kv	Keesara	15.15	15.55	00.40		11KV Line cut at Venkat Reddy Angur Thota	-
2		Narapally	Narapally Industrial	11kv	Keesara	14.55	15.55	01.00		11KV Polymer Disc failed at Venkatadri Township Phase-III	-
1	HYD N	Prashanth Nagar	Time Tek	11kv	VI	15.15	17.10	01.55	EL	Pin Insulator flash over at 1st line AB Switch	-----
1	HYD C	Bathkammakunta	Ramalayam	11kv	II	09.08	10.10	01.02	EL	Disc Insulator flash over at SS	-----
2		Chilkaiguda	Parsigutta	11kv	II	16.25	17.40	01.15	OL-Y&Bph	Coconut tree branches fallen on lines at EWS Nala	-----
3		Zaminstanpur	Balaji Nagar	11kv	II	23.40	00.48	01.08	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Jamiya Osmania for