

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403		11		11		11			
8	Hyd	194	1044		9		9		9			
	Total	606	3055	0	27	0	27	0	27	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	1	5	1	5	1			
2	NLG	144	988	1	10	1	10	1	10			
3	MDK	107	933	4	2	4	2	4	2			
4	SDPT				22		22		22			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	10	35	10	35	10	35	0	0	
	Grand Total	1082	6468	10	62	10	62	10	62	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.06.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SVS Edira	33KV	Mahabubnagar	00.23	00.45	00.22	E/L&O/L	Jumper cut Near 132KV MBNR	Mahabubnagar	Alternate supply arranged From 33 KV Jadcherla at 00:45Hrs.
2		Polepally	Polepally	33KV	Jadcherla	00.18	06.15	05.57	E/L	Tree Fallen on the Line	Polepally	NO
3		Nagarkurnool	Manthathi	33KV	Nagarkurnool	01.15	10.25	09.10	E/L	Tree Fallen on the Line	Nagarkurnool	NO
4		Wanaparthy	Kothakota	33KV	Wanaparthy	08.30	09.05	00.35	E/L	Squarrel Fallen on the line Near Chintala Road	Wanaparthy	Alternate supply arranged form 132 KV Thirumalaipally to 33 KV kothakota
5		Alampur	Undavelly	33KV	Gadwal	06.05	10.30	04.25	E/L	Insulator Damaged	Alampur	NO
1	NLG	Huzurnagar	Burugadda	33KV	Huzurnagar	05.00	10.25	05.25	EL/OL	33Kv Insulator Failed		-
1	MDK	Narayankhed	Kalher	33KV	Jogipet	02.25	11.20	08.55		BD due to Tree fallen on line		-
2		Narayankhed	Poosalpad	33KV	Jogipet	05.45	07.45	02.00		BD due to Insulator failed		-
3		Gummadidala	AFA	33KV	Patancheru	12.40	14.25	01.45		BD due to Pin binding failed		-
4		Singoor	Mudmanik	33KV	Jogipet	03.16	07.40	04.24		BD due to Insulator failed		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Mothiganpur	11KV	Jadcherla	06.40	14.00	07.20		Due to 11 KV Disc Failed near Nandaram (V)	-
1	NLG	Kopple	Thurngathurthy	11KV	Nalgonda	03.15	07.50	04.35	O/L	Tree Fallen on the 11 KV Line	-
2		Kopple	Bheemavaram	11KV	Nalgonda	05.45	12.04	06.19	E/L	11KV KV Jumper Cut at Bheemaram Rice Mill	-
3		K.M.Pally	Chennaram	11KV	Devarakonda	07.00	12.00	05.00	E/L	11 KV 1 No Disc & 1 No Insulater Failed	-
4		K.B.Pally	S.P.Thanda	11KV	Devarakonda	06.00	11.00	05.00	E/L	HT/LT	-
5		Mellavai	Revalli	11KV	Devarakonda	06.00	08.30	02.30	E/L	Moviement Fault	-
6		Thungathurthy	Ganugubanda	11KV	Suryapet	06.20	09.10	02.50	E/L	Insulator flashover	-
7		Bathavolu	Channarigudem	11KV	Huzurnagar	04.20	06.10	01.30	E/L	11Kv Line Snapped	-
8		BNL Thanda	Varadhapuram	11KV	Huzurnagar	11.20	12.40	01.20	E/L	11Kv Line Snapped	-
9		Venkatapur	Velupally	11KV	Bhongir	04.30	14.00	09.30	EL/OL	11kv Line sanpped near Velupally Village 3 phase B/d single phase ok	-
10		Yennaram	Suraram	11KV	Choutuppal	07.45	09.45	02.00	EL/OL	11kv Insulator failed at SS-3 near Bt.Pally (V)	-
1	MDK	EPIP-III	Jeevan Polymer	11KV	Sangareddy	02.35	06.55	04.20		BD due to Tree branches fallen on line	-
2		Pati	Ionnex	11KV	Patancheru	02.40	08.45	06.05		BD due to Tree branches fallen on line	-
1	SDPT	Husnabad	Pandilla	11KV	Husnabad	15.10	17.25	02.15		Insulator failure same rectified	-
2		Gouravelly	Gouravelly Express	11KV	Husnabad	09.35	10.45	01.10		Disc failure same rectified	-
3		Gouravelly	Gudatipally	11KV	Husnabad	14.45	18.00	03.15		Lines touched same rectified	-
4		WARDARAJPUR SS	SHIVARVENKATAPUR FEEDER	11KV	Gajwel	05.00	08.45	03.45		25KVA DTR FAILED	-
5				11KV	Gajwel					ALL FEEDERS ARE NORMAL	-
6		MULUGU SS	NAGIREDDYPALLY FEEDER	11KV	Gajwel	09.05	11.35	02.30		11KV LINE CUT	-
7		VANTIMAMIDI SS	ZAPTISINGAIPALLY FEEDER	11KV	Gajwel	08.48	17.24	06.36		INSULATOR FAILED	-
8				11KV	Gajwel					ALL FEEDERS ARE NORMAL	-
9		RAMPUR SS	RAMPUR FEEDER	11KV	Gajwel	17.15	16.40	01.25		INSULATOR FAILED	-
10		LINGAPUR SS	LINGAPUR FEEDER	11KV	Gajwel	15.45	16.35	00.50		CABLE BURNED	-
11		LINGAPUR SS	VENKATRAOPET FEEDER	11KV	Gajwel	11.44	13.55	02.11		INSULATOR FAILED	-
12		DOMMATA SS	SURAMPALLY FEEDER	11KV	Gajwel	13.00	14.11	01.11		SINCCE SQUIRREL TOUCHED THE 11KV LINE. JUMPER HAS CUT DOWN	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
13	SDPT	GURRALASOFA SS	MASANPALLY FEEDER	11KV	Gajwel	04.38	11.00	07.28		INSULATOR FAILED	-
14		GURRALASOFA SS	VADDEPALLY FEEDER	11KV	Gajwel	08.50	12.00	03.10		DISC FAILED	-
15		ANAJIPUR SS	MANTHUR FEEDER	11KV	Gajwel	12.20	13.05	00.45		SINCCE SQUIRREL TOUCHED THE 11KV LINE. JUMPER HAS CUT DOWN	-
16		Irkode	Irkode	11KV	Siddipet	13.25	14.45	01.20		B/D Tree branches fall on the line & LC.No.15182	-
17		Jakkapur	Gopulapur	11KV	Siddipet	05.12	09.03	03.51		B/D Insulater fail & LC.No.24043	-
18		Dharamjipet	Yegondaswamy	11KV	Siddipet	03.10	09.50	06.40		B/D Insulater fail & LC.No.21474	-
19		Dharamjipet	Lachapet	11KV	Siddipet	03.10	11.15	08.05		B/D Tree branches fall on the line & LC.No.21475	-
20		Mirdoddy	Mirdoddy	11KV	Siddipet	04.45	08.00	03.15		B/D Tree branches fall on the line	-
21		Mirdoddy	Andhey	11KV	Siddipet	04.45	11.20	06.35		B/D Tree branches fall on the line	-
22		Mirdoddy	Kasulabad	11KV	Siddipet	04.45	11.20	06.35		B/D Tree branches fall on the line	-
1	RR S	Chandanagar	Rail Vihar	11KV	Gachibowli	02.00	03.00	01.00		11KV Line AB Switch Jumper Cut at Brindavan Hotel.	-
2		ESCI	Lumbini park	11KV	Kondapur	03.18	06.00	02.42		11kv pin Insulator failed at Vasista Apartments and 11kv LABS Jumper touched to Earth Wire at HDFC Bank.	-
1	RR N	Subhash Nagar	Pragha Tools	11KV	Medchal	05.40	07.05	01.25	EL	Bird fallen on the 11KV Line & HG fuse Insulator failed at BHEL Vista	-
2		GP Pally	GP Pally	11KV	Medchal	04.30	06.00	01.30	EL/OL	11KV Pin Insulator failed & Disc at Venkateswara Pipes Company	-
3		Uddamarry	Usharpally	11KV	Medchal	07.25	08.35	01.10	EL/OL	Bird fallen on the 11KV Line at Vakhil Thota, near SS	-
4		Ravalkole	Ravalkole	11KV	Medchal	06.30	07.58	01.28	EL	Tree Branch fallen on the 11KV Line at Ravalkole Village	-
5		ICICI	Bharat Bio Tech	11KV	Medchal	02.00	05.20	03.20	EL/OL	2 Nos. Pin Insulators Failed at Near SS	-
1	RR E	Nacharam indore	Ramreddy nagar	11KV	Habsiguda	03.55	05.19	01.24		Pin insulator fail at Ramulla DTR Ramreddy nagar	-
2		Idauppall	Ramreddy nagar	11KV	Habsiguda	01.02	02.10	01.08		Kamakshipuram feeder cable touched to 11kv Ramreddy feeder at TV colony	-
3		Yapral	Yapral	11KV	Sainikpuri	04.50	06.10	01.20		Tree branches fallen on 11Kv line at Sri Devi Kalyan Estate (Artisian Shankar)	-
4		Yapral	Pradhamapuri	11KV	Sainikpuri	04.55	06.55	02.00		11KV Pin Insulator failed at Mythri Enclave (Artisian Devi Lal)	-
5		Jana Priya	High Tension	11KV	Sainikpuri	06.00	07.20	01.20		Tree branches fallen on 11Kv line at Netaji Nagar Chrowsatha (LM Venkatesh)	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
6	RR E	P&T colony	NIN	11KV	Keesara	01.25	04.45	03.20		11KV Line Sanpaed at Budda nagar	-
7		Narapally	P.Singaram	11KV	Keesara	05.05	06.05	01.00		Disk fail at Chowdariguda	
8		Balaji nagar	Laxmi narshima	11KV	Keesara	06.15	10.25	04.10		Disk fail at laxmi narshima kaman	
9		Chengicherla	Chengicherla	11KV	Keesara	04.10	04.55	00.45		Insulator fail at Hema nagar	-
10		Chengicherla	Myvillas	11KV	Keesara	01.30	03.00	01.30		11KV Line Sanpped at Kankadurga raod	-
11		GKSR	Kondapur	11KV	Keesara	01.30	03.30	02.00		Coconut tree branches fallen on 11kv line kareemguda	-
1	HYD N	Jubilee Hills	Art Gallery	11KV	Banjarahills	00.50	02.30	01.40	EL,OL-R&Bph	No Visible Fault (Due to Rain)	-
2		Madhapur	Value Lab	11KV	Banjarahills	01.10	02.45	01.35	EL	HT Jumper cut at Jayabheri Kaman	-
3		Jubilee Hills	Art Gallery	11KV	Banjarahills	03.05	04.30	01.25	EL	No Visible Fault (Due to Rain)	-
4		Ayyappa Society	Image Garden	11KV	Banjarahills	04.20	05.50	01.30	EL,OL-Bph	Pin Insulator flash over at LOT Mobiles	-
5		Macha Bollaram	Balaji Rice Mill	11KV	Bowenpally	04.30	06.24	01.54	EL	Pin Insulator flash over & tree branches fallen on lines at Macha Bollaram	-
1	HYD C	Karwan	Langer House OH	11KV	Medhipatnam	00.45	02.05	01.20	All Indication	Tree branches fallen on lines at Mehindi Colony	-
2		Narayanguda	Narayanguda	11KV	Azamabad	04.20	05.50	01.30	EL,OL-Rph	Tree branches fallen on lines at Nala	-
3		Bathkammakunta	Shivalayam	11KV	Azamabad	04.36	06.48	02.12	EL	Tree branches fallen on lines at Narshimula Basthi	-
4		Toli Chowki	Hakimsha	11KV	Medhipatnam	15.06	16.20	01.14	EL,OL-Rph	Twisted Lines at Hakimsha Colony	-