

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988	4	28	4	28	4	28			
3	MDK	107	933	2	10	2	10	2	10			
4	SDPT				14		14		14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	7	54	7	54	7	54	0	0	
	Grand Total	1082	6468	7	57	7	57	7	57	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.06.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Pebbair	33KV	Wanaparthy	16.22	19.50	03.28	E/L	R Phase Jumper cut and Replacement at 132KV Wanaparthy SS	Wanaparthy	Alternate supply arranged form 132KV SS Thirumalaipally to 33KV Willamkonda
1	NLG	Mattampally	Raghunadhaplem	33KV	Huzurnagar	02.00	08.00	06.00	EL/OL	Due to 33Kv line line cutted	Mattampally	-
2		Haliya	33KV Peddavoora	33KV	Miryalaguda	08.30	13.15	04.45	EL/OL	Poles Leaning	Haliya	33KV Rajavaram feeder
3		Haliya	33KV Yacharam	33KV	Miryalaguda	08.30	13.15	04.45	EL/OL	Poles Leaning	Haliya	33KV Rajavaram feeder
4		Suryapet	Nuthankal	33KV	Suryapet	00.25	08.55	08.30	EL	2Nos Insulators flashover	Suryapet	-
1	MDK	Narayankhed	Kalheer	33KV	Jogipet	03.25	08.13	04.48		B/d due to Pin Insulator failure		-
2		Singoor	Mudimanik	33KV	Jogipet	03.15	07.30	04.15		B/d due to Insulator failure		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Annasagar	Town	11KV	Jadcherla	04.00	06.13	02.13		Insulator fail near Annasagar	-
2		Pomal	Ammapur	11KV	Jadcherla	09.20	13.40	04.20		11KV Wire cut near Pomal	-
1	NLG	N Annaram	Lingala	11KV	Suryapet	06.00	08.00	02.00	E/L	Tree Branch fallen on the line	-
2		Yerkaram	Ramannagudem	11KV	Suryapet	05.30	09.04	03.34	E/L	Insulator flashover	
3		Jalalpuram	Velishala	11KV	Suryapet	10.00	13.15	03.15	E/L	Insulator flashover and Line melt	
4		Palakaveedu	Sajjapuram	11KV	Huzurnagar	05.30	08.30	03.00	EL	Due to 11 KV LINE SNAPPED	
5		Munagala	Turkagudem	11KV	Huzurnagar	07.00	10.00	03.00	EL	Due to 11 KV LINE jumper cutted	
6		Aitipamula	Ch.Annaram	11KV	Nalgonda	08.00	10.40	02.40	EL	Insulator Failure	
7		Velugupally	Ithavarigudem	11KV	Nalgonda	06.00	09.50	03.50	EL	Insulator Failure	
8		Devarakonda	K.B.Pally	11KV	Devarakonda	03.00	08.00	05.00	EL	11 KV Line Cutt	
9		Cherukupally	Cherukupally	11KV	Devarakonda	06.00	09.00	03.00	EL	HT/LT	
10		Marriguda	Vattipally	11KV	Devarakonda	05.00	09.15	04.15	EL	HT/LT	
11		Nampally	M.R.Pally	11KV	Devarakonda	04.00	08.00	04.00	EL	11 KV Jumper Cutt	
12		Nampally	Mandapuram	11KV	Devarakonda	06.00	08.00	02.00	EL	AB Switch Male & Female Fault	
13		Haliya	Naidpalem	11KV	Miryalaguda	05.30	08.45	03.15	EL	11KV conductor sanpped	
14		Haliya	Thirumalgiri	11KV	Miryalaguda	05.20	06.55	01.35	EL	11KV Insulator failed	
15		Alwala	P.V.Kunta	11KV	Miryalaguda	06.40	08.20	01.40	EL	11KV Insulator failed	
16		Pulimamidi	Pulimamidi	11KV	Miryalaguda	08.30	10.40	02.10	EL	11KV conductor sanpped	
17		Pulimamidi	Sreenadapuram	11KV	Miryalaguda	07.45	09.15	01.30	EL	11KV Disc failed	
18		B.Annaram	Dilawarpoor	11KV	Miryalaguda	04.20	06.30	02.10	EL	11KV Insulator failed	-
19		Kannekal	Dharmapuram	11KV	Miryalaguda	06.00	09.00	03.00	EL	11KV Insulator failed	-
20		Matoor	Ragadapa	11KV	Miryalaguda	03.00	06.10	03.10	EL	11KV conductor sanpped	-
21		MR.Gudem	Baswapur	11KV	Bhongir	04.35	07.34	02.59	EL	11 kv Insulator failed at Church back side near Muthireddy gudem village	-
22		MR.Gudem	Indl	11KV	Bhongir	07.20	09.00	01.40	EL	11 kv Line snapped & 11kv Insulator Failed near Mutthireddy gudem village	-
23		Mothkur	Mothkur rural	11KV	Bhongir	20.10	07.00	10.50	EL	11 kv Insulator failed near Mothkur village	-
24		Addagudur	Dharmaram	11KV	Bhongir	00.00	07.40	07.40	EL	11 KV Line melt near Kotamarthy village. 3 Phase B/d single phase ok	
25		Addagudur	Ramaram	11KV	Bhongir	00.00	11.20	11.20	EL	SS-13 25kva DTR Failed Phase B/d single phase ok	
26		Kapraipally	Rahimkhanpet	11KV	Bhongir	22.10	12.45	14.35	EL	11kv Disc Failed near Rahemmkanpet Village 3 Phase B/d single phase ok	
27		Yennaram	Palliwada	11KV	Choutuppal	07.30	09.30	02.00	EL	11 kv Disc failed near Palliwada village	
28		Choutuppal	Thangdapally	11KV	Choutuppal	08.30	12.00	03.30	EL	11kv Line Sanpped near Sub_station Inside	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MDK	Sangareddy Town -II	No.III	11KV	Sangareddy	11.10	12.20	01.10		B/d due to Jumper cut	-
2		Sangareddy Rural	Balaji	11KV	Sangareddy	03.20	07.40	04.20		B/d due to Tree branches fallen on the line	-
3		Sangareddy Rural	Kothlapur	11KV	Sangareddy	04.35	05.32	00.57		B/d due to Tree branches fallen on the line	-
4		Sadasivapet	Nandi Kandi	11KV	Sangareddy	02.14	05.00	02.46		B/d due to Insulator failure	-
5		Sadasivapet	TSM	11KV	Sangareddy	02.14	06.00	03.46		B/d due to Insulator failure	-
6		Sadasivapet	Town-II	11KV	Sangareddy	02.12	06.36	04.24		B/d due to Jumper cut	-
7		EPIP-III	Tychy Diecast	11KV	Sangareddy	04.20	08.00	03.40		B/d due to Tree branches fallen on the line	-
8		Bollaram-I	Kythan	11KV	Patancheru	04.30	07.55	03.25		B/d due to Jumper cut	-
9		Bollaram-I	Soubhagya	11KV	Patancheru	06.30	10.08	03.38		B/d due to Conductor snapped	-
10		Bollaram-I	Sulaxshana-I	11KV	Patancheru	07.55	10.00	02.05		B/d due to Conductor snapped	-
1	SDPT	Laxmidivipally	Laxmidivipally	11KV	Siddipet	17:00	19:34	02:34		B/D 11 KV Line Cut LC No.24151	-
2		Laxmidivipally	Ibrahimpur	11KV	Siddipet	06:00	09:00	03:00		B/D Insulater failed LC No.11320	-
3		Narayanraopet	Rajannagudi	11KV	Siddipet	07:30	14:10	06:40		B/D Insulater failed LC No.11321	-
4		Narayanraopet	Beerappagudi	11KV	Siddipet	08:40	11:20	02:40		B/D Bird foll down LC No.10591	-
5		Chandlapur	Chandlapur	11KV	Siddipet	08:34	10:25	01:51		B/D Insulater failed LC No.10590	-
6		Chandlapur	Gangapur	11KV	Siddipet	10:10	11:10	01:00		B/D LT Line cut LC No.15899	-
7		Habshipur	Habshipur	11KV	Siddipet	15:02	16:34	01:32		B/D 11 KV Line cut LC No.22001	-
8		Gambeerpur	Potharam	11KV	Siddipet	08:00	08:59	00:59		B/D 11 KV Juper cut LC No.4349	-
9		Gambeerpur	Potharam	11KV	Siddipet	04:30	09:00	04:30		B/D 11 KV Line cut	-
10		BANDARAM SS	BANDARAM AGL	11KV	Gajwel	11.54	13.50	02.04		LT LINE WORK	-
11		BANDARAM SS	ANKIREDDYPALLY AGL	11KV	Gajwel	16.18	18.02	01.44		11KV LINE WORK	-
12		THIMMAREDDYPALLY SS	LAKUDARAM FEEDER	11KV	Gajwel	13.25	18.15	04.50		11KV INSULATOR FAILED	-
13		BEGAMPET SS	BEGAMPET FEEDER	11KV	Gajwel	16.25	18.15	01.50		TREE BRANCH WAS FALLEN	-
14		ANAJIPUR SS	MANTHUR FEEDER	11KV	Gajwel	12.00	08.45	08.45		TREE BRANCH WAS FALLEN	-
1	RR S	Gachibowli	Kothguda	11KV	Kondapur	07.15	09.10	01.55	BD	11kv Cable failed at Masjed banda (Load add on Kalajyothy feeder)	-
1	RR N	Jagathgirigutta	Jagathgirigutta	11KV	Medchal	17.30	18.30	01.00		11KV AB Cable endkit failed at Anjaiah Nagar	-
1	HYD C	Vittalwadi	Gandhi Kuteer	11KV	Azamabad	04.12	06.20	02.08	EL,OL-Bph	Tree branches fallen on lines, RMU Lug B/O, Jumper cut & AB Switch fault at Vittalwadi	-