

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	2	4	2	4	2	4			
	Total	606	3055	2	7	2	7	2	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		3		3		3			
3	MDK	107	933		1		1		1			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	2	16	2	16	2	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.06.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD S	220KV Ch' Gutta	Laxmi Nagar	11KV	Malakpet	22.40	22.50	00.10	EL,OL-Y&Bph	Cable fault	Laxmi Nagar	Loads transferred onto 132KV Moosarambagh SS via 33KV Malakpet B-Block fdr
1	HYD C	132KV Imlibun	Gosha Mahal (partial bit)	11KV	Asif Ngr	06.35	06.40	00.05	OL-Bph	2Nos. Straight through Joints failed	Gosha Mahal (partial bit)	Loads transferred onto 33KV Imlibun - Seetharam Bagh feeder & at 21.00 hrs. 33KV Seetharambagh - Gosha Mahal partial bit charged stood OK

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 05.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Burgupally	11KV	Jadcherla	10.50	13.00	02.10		11 KV Disc Failed near Allor Village	-
2		Mothiganpur	Mothiganpur	11KV	Jadcherla	12.04	13.40	01.36		Tree Fallen on the 11KV line near mothiganpur Village	-
1	NLG	Thungathurthy	Bandaramaram	11KV	Suryapet	05.50	09.00	03.10	E/L	Insulator failed	-
2		Gurraladandi	Jampally	11KV	Bhongir	07.00	10.39	03.39	EL/OL	11 kv Line snapped near Jampally village	-
3		Chamapur	Chamapur	11KV	Bhongir	04.00	06.40	02.40	EL/OL	100 kva DTR Failed near Chamapur village	-
1	MDK	Patancheru Town	MIA-II	11KV	Patancheru	11.30	12.55	01.25		B/D due to Jumper cut	-
1	SDP	Peddachepyal	Peddachepyal	11KV	Siddipet	08.30	16.30	08.00		B/D Tree branches fallen	-
2		MULUGU SS	NAGIREDDYPALLY FEEDER	11KV	Gajwel	15.40	16.40	01.00		DISC FAILED	-
3		THIPPARAM SS	MUDDAPUR FEEDER	11KV	Gajwel	09.00	12.00	03.00		HT BY LT	-
1	RR N	HMT	Manikya Nagar	11KV	Medchal	06.00	06.47	00.47	BD	Bird fallen on the 11KV Line & HG fuse Insulator failed at BHEL Vista	-
1	RR E	Mallapur 2	Ashok nagar	11KV	Habsiguda	15.03	16.20	01.17		Ashok nagar feeder UG cable fail & Back feeding to noma	-
2		NGRI	Kalyanpuri	11KV	Habsiguda	18.30	19.26	00.56		Cameleon (Thonda) fallen on 11kvline & touched to X arm at pochamma temple	-
1	HYD N	Clock Tower	Sangeeth	11KV	V	17.00	18.30	01.30	EL,OL-Rph	HT top Jumper cut at D.C. Office	-----
2		Lalaguda	Vijayapuri	11KV	V	17.06	19.15	02.09	EL	Pin Insulator flash over at SV Land Mark, Vijayapuri	Arranged B/F on 11KV Chenna Reddy feeder
3		Chinna Thokatta	Hasmathpet	11KV	VI	23.26	01.01	01.35	EL,OL-Rph	No Visible Fault	Partial charged & partial loads added on 11KV Satya Sai Enclave fdr
1	HYD S	Malakpet	Prabhath	11KV	IX	22.45	23.55	01.10	EL,OL-Yph	HG fuse B/O at Railway Track	-