

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	10	1	10	1	10	0	0	
	Grand Total	1082	6468	1	12	1	12	1	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.06.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Thukkapur	Lingapur	33KV	Gajwel	7:30	12:10	4:40		Insulator failed	Lingapur	No

TSSPDCL - LMRC / Corporate office

Date: 07.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gangapur	Gangapur	11KV	Jadcherla	13.00	13.40	00.40		HT/LT near Kodga (V) side	No
1	NLG	Thurkapally	Thurkapally	11KV	Nalgonda	4:00	9:30	5:30	O/L	Tree branch fallen on the line	No
2		Anneparthi	Bettalian	11KV	Nalgonda	03.00	07.00	04.00	O/L	Tree branch fallen on the line	No
3		Nakkalapally	Shapally	11KV	Nalgonda	10.55	12.25	01.30	E/L	11KV Insulator failed	No
4		Kattangur	Powerloom	11KV	Nalgonda	13.50	14.25	00.35	E/L	Thatimatta fallen on the line	No
5		Yacharam	Haliya	11KV	Miryalaguda	14.35	16.10	01.35	E/L	Jumper cut near Yacharam village	No
6		Yerkaram	Raju naik Thanda	11KV	Suryapet	08.42	11.35	02.53	E/L	Insulator failed	No
7		N.B.Gudem	Redlakunta	11KV	Huzurnagar	7:30	9:00	1:30	EL	11KV Jumper cut	No
1	SDPT	Doulthabad	Sheripally Bandaram	11KV	Gajwel	8:56	9:20	0:16		DTR Work	No
2		Thukkapur	Yellareddy Pet	11KV	Gajwel	14.00	16.05	02.05		Insulator failed	No
1	RR N	Subhash Nagar	Padma Nagar	11KV	Medchal	6:01	7:40	1:39		HT Service problem at Padma Nagar	No
1	RR E	Vinayak Nagar	Devi Nagar	11KV	Sainikpuri	1:15	2:25	1:10		HG fuse blown at Krupa complex at Block 18	No