

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550	1	16	1	16	1	16			
7	RR(E)	168	403		16		16		16			
8	Hyd	194	1044	1	27	1	27	1	27			
	Total	606	3055	2	61	2	61	2	61	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		25		25		25			
3	MDK	107	933		3		3		3			
4	SDPT				30		30		30			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	60	1	60	1	60	0	0	
	Grand Total	1082	6468	3	121	3	121	3	121	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.06.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Thanrnikal	33KV	Nagarkurnool	08.10	10.55	02.45	E/L&O/L	Pin Insulator Replacement at Nagarkurnool Road	Thanrnikal	-
1	RR N	132KV Medchal	33KV Medchal-I	33KV	Medchal	04.10	05.00	00.50	BD	33KV Cable End kit Failed	33KV Medchal-I	-
1	HYD N	132KV Erragadda	Bora Banda	33KV	Allwyn	20.56	21.01	00.05	OL-Rph	Cable damaged by GHMC wing near NRR Puram Site-I, Fish Market	Bora Banda	Loads transferred onto 132KV Erragadda SS via 33KV IDPL-I fdr

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 11.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Prdda Revally	Chinna Revally	11KV	Jadcherla	05.20	07.10	01.50		11KV Jumper cut near Pedda Chelka thanda Village	-
2		Velgomla	Velgomla	11KV	Jadcherla	10.30	13.05	02.35		11KV Jumper cut near Kothur Village	-
1	NLG	Nemmikal	Enubamula	11KV	Suryapet	06.00	08.00	02.00	E/L	Insulator flashover	-
2		Yerkaram	Balemla	11KV	Suryapet	02.30	07.10	04.40	E/L	Insulator flashover	-
3		Aipoor	Kotapahad	11KV	Suryapet	08.30	11.50	03.20	E/L	Jumper cut	-
4		Annaram	Kothagudem	11KV	Suryapet	06.00	08.50	02.50	E/L	Insulator flashover	-
5		Bibigudem	Chivemla Agl	11KV	Suryapet	04.00	07.30	03.30	E/L	Insulator flashover	-
6		Garidepally	Ponugodu	11KV	Huzurnagar	03.45	06.50	03.05	EL	Due to 11kv Jumper cutted	-
7		Nadigudem	Ramapuram	11KV	Huzurnagar	05.00	08.00	03.00	EL	Due to 11kv Disk Failure	-
8		Bethavolu	chennarigudem	11KV	Huzurnagar	23.50	01.50	02.00	EL	Due to 11kv Insulator failure	-
9		Gurrampode	Thenepally	11KV	Devarakonda	04.00	07.40	03.40	EL	Tree Fllowen	-
10		Gurrampode	Chamaled	11KV	Devarakonda	06.00	10.00	04.00	EL	11 KV Jumper Cutt	-
11		Mellavai	Devathpally	11KV	Devarakonda	05.00	10.00	05.00	EL	15KVA DTR Failed Devathpally SC Colony	-
12		Madanapuram	Madanapuram	11KV	Devarakonda	04.00	09.00	05.00	EL	11 KV 1 No Insulator failed	-
13		Chinthapally	Varakala	11KV	Devarakonda	05.00	08.00	03.00	EL	11 KV Jumper Cutt	-
14		Muppam	Vootkur	11KV	Miryalaguda	09.30	11.15	01.45	EL	11 KV Jumper Cutt	-
15		Nandipad	Tank Thnada	11KV	Miryalaguda	11.38	13.08	01.30	EL	Tree Fallen	-
16		NG.Bandal	Gandamalla	11KV	Bhongir	02.15	10.45	08.30	EL	11 kv Insulator failed near Gandamalla village	-
17		Kondamadugu	Anand agro	11KV	Bhongir	19.30	23.59	04.29	EL	11 kv Disc failed near Kondamadugu village	-
18		Kondamadugu	Anand agro	11KV	Bhongir	00.30	08.55	08.25	EL	11 kv Pin Insulator failed near Kondamadugu village	-
19		Venkiryala	Venkiryala	11KV	Bhongir	05.40	09.06	03.26	EL	11 kv Disc failed near Uyyala kunta village.	-
20		Rajapeta	Nemila	11KV	Bhongir	05.00	11.15	06.15	EL	2 no's 11 kv Insulators failed & Tree branch fallen at line near Nemila village	-
21		Raghunathpur	Raghunathpur Agl	11KV	Bhongir	06.00	11.30	05.30	EL	11kv Disc Failed near Raghunathpur Village 3 Phase B/d single phase ok	-
22		Pamukunta	Pamukunta	11KV	Bhongir	06.00	11.00	05.00	EL	11 kv Line snapped at Malla reddy well near Malla gudem village	-
23		Motakondur	Vartoor	11KV	Bhongir	01.00	08.30	07.30	EL	11 kv Disc failed near Vartoor village	-
24		Azeempet	Kanchanapally	11KV	Bhongir	05.00	09.00	04.00	EL	11 kv Insulator failed at SS-7 near Kanchanapally village	-
25		Choutuppal	Jublakapilly	11KV	Choutuppal	00.00	09.35	09.35	EL	11 kv Insulator failed near Lingareddy gudem	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MDK	Sangareddy Town-II	No-III	11KV	Sangareddy	05.22	06.00	00.38		BD due to Tree fallen on line	-
2		Faslwadi	MNR	11KV	Sangareddy	14.10	15.35	01.25		BD Conductor snapped	-
3		Bollaram-I	Salgutty	11KV	Patancheru	01.05	01.57	00.52		BD due to Insulator failed	-
1	SDP	Mustabad X-Road	Gadicherlapally Agl	11KV	Siddipet	12.30	13.30	01.00		B/D-Disk fail- Rectified	-
2		Ankshapur	Khanapur Agl	11KV	Siddipet	05.02	07.05	02.03		B/D-Disk fail- Rectified	-
3		Raghavapur	Raorukula	11KV	Siddipet	00.40	07.27	06.47		B/D- Tree bunches fallen-Rectified	-
4		Dharmajipet	Lachapet	11KV	Siddipet	00.00	09.20	09.20		B/D-Tree bunches fallen-Rectified	-
5		Dharmajipet	Aegonda swamy	11KV	Siddipet	00.00	10.30	10.30		B/D-Tree bunches fallen-Rectified	-
6		Dubbak IPDS	Chervapur Agl	11KV	Siddipet	00.00	10.54	10.54		B/D-11 KV line cut-Rectified	-
7		GAJWEL	TOWN-1 (LC.NO:7266)	11KV	Gajwel	10.30	07.15	08.45		11KVA DISK & INSULATOR FAILED	-
8		GAJWEL	MUTRAJ PALLY (LC.NO:7269)	11KV	Gajwel	12.40	13.45	01.05		INSULATOR FAILED	-
9		MUNIGADAPA	VATTIPALLY (LC.NO:5641)	11KV	Gajwel	00.00	10.55	09.01		DISK FAILED	-
10		CHATLA PALLY	CHATLA PALLY AGL (LC.NO: 5720)	11KV	Gajwel	12.11	15.13	03.02		INSULATOR FAILED	-
11		THIGULLA	INDUSTRILA (LC.NO:6832)	11KV	Gajwel	13.58	17.30	03.32		AB SWITCH REPAIRED	-
12		PREGNAPUR	TOWN (LC.NO:19626)	11KV	Gajwel	01.47	06.45	05.02		JUMPER CUT	-
13		MARKOOK	BHAVANADHAPUR (LC.NO:25272)	11KV	Gajwel	08.00	09.30	01.30		11 KV WIRE CUT	-
14		MARKOOK	MARKOOK AGL (LC.NO:25274)	11KV	Gajwel	10.20	11.20	01.00		11 KV WIRE CUT	-
15		VARDHARAJ PUR	SHIVARU VENKATAPUR (LC.NO:25074)	11KV	Gajwel	07.30	08.10	00.40		TREE BRANCH FELL DOWN ON THE 11 KV LINE	-
16		ERRAVALLY	ERRAVALLY AGL (LC.NO:26309)	11KV	Gajwel	01.00	07.00	06.00		DISK FAILED	-
17		KARKAPATLA	KARKAPATLA AGL (LC.NO: 30653)	11KV	Gajwel	20.44	12.20	15.36		DISK & INSULATOR FAILED	-
18		WARGAL SS	TOWN (LC.NO:13968)	11KV	Gajwel	19.40	06.00	10.20		INSULATORE BURN	-
19		GOWRARAM	GOWRARAM AGL (LC.NO: 40182)	11KV	Gajwel	22.10	16.20	18.10		DISK FAILED	-
20		GOWRARAM	PATHUR (LC.NO: 40183)	11KV	Gajwel	13.10	14.10	01.00		TREE BRANCH FELL DOWN ON THE 11 KV LINE	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
21		VATTIMAMIDI	INDUSTRILA (LC.NO:31023)	11KV	Gajwel	09.15	12.40	03.25		11 KV LINE CUT	-
22		THUNIKI BOLLARAM	ACHAIPALLY (LC.NO:)	11KV	Gajwel	13.10	15.10	02.00		DISK FAILED	-
23		THIPPARAM	INDUSTRIAL (LC.NO28019)	11KV	Gajwel	15.00	16.15	01.15		TREE BRANCH FELL DOWN ON THE 11 KV LINE	-
24		MARPADAGA	KHAMMAM PALLY(LC.NO:28160)	11KV	Gajwel	22.30	08.30	10.00		11 KV DISK FAILED	-
25		MARPADAGA	MARPADAGA AGL-II (LC.NO28163)	11KV	Gajwel	08.30	16.00	07.30		JUMPER CUT	-
26		GURRALASOPA	WADDEPALLY (LC.NO4353)	11KV	Gajwel	08.00	12.08	04.08		DISK FAILED	-
27		GURRALASOPA	WADDEPALLY (LC.NO4355)	11KV	Gajwel	12.33	14.12	01.39		DISK FAILED	-
28		THUKKAPUR	THUKKAPUR (LC.NO:6159)	11KV	Gajwel	00.40	09.00	08.20		POLE FELL DOWN	-
29		THUKKAPUR	THOGUTA AGL (LC.NO:6160)	11KV	Gajwel	08.30	14.20	05.50		11 KV WIRE CUT	-
30		PALLEPAHAD	PALLEPAHAD (LC.NO: 08217)	11KV	Gajwel	04.30	06.30	02.00		11 KV WIRE CUT	-
1	RR S	IIIT	Kindriya Vihar	11KV	Gachibowli	02.25	04.15	01.50	BD	Road crossing cable failed at Himagiri Hospital	-
2		Lanco Hills	Chitrapuri Colony	11KV	Gachibowli	18.47	20.46	01.59	BD	11Kv cable failed at Chitrapuri crashar	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Vijayanagar colony	Allwyn colony	11KV	Kukatpally	02.40	04.20	01.40	BD	11kv AB Cable endkit failure at Sarovar aptt	-
2		Jeedimetla SS II	Apuroopa colony	11KV	Jeedimetla	08.20	10.00	01.40	BD	AB Cable, Jumper snapped near SRC Nayik nagar park	-
3		Jeedimetla SS II	Apuroopa colony	11KV	Jeedimetla	10.50	12.25	01.35	BD	Pin insulator failure at Modi builders	-
4		HMT	Ganesh Nagar	11KV	Medchal	00.05	00.55	00.50	BD	11KV Junper cut and replaced at Cherukupalli Clolony	-
5		Subhash Nagar	Jairam Nagar	11KV	Medchal	10.28	11.30	01.02	BD	Tree Branch fallen on the 11KV Line at Kowtinya Club	-
6		HMT	Ganesh Nagar	11KV	Medchal	01.10	02.00	00.50	BD	11KV Jumper cut and replaced at Kalpana Society	-
7		Dp Pally SS II	Indian oil	11KV	Jeedimetla	02.20	05.30	03.10	BD	UG cable failure at Gandimaisamma	-
8		Kolthur	Anatharam	11KV	Medchal	01.50	04.50	03.00	BD	11KV Disc Failed and replaced at IDA Tower,Kolthur Village	-
9		Athiwelly	Padmaja	11KV	Medchal	07.00	10.35	03.35	BD	Tree Branch fallen on the 11KV Line at Bewan Function Hall	-
10		Bommarajpet	Ramalayam	11KV	Medchal	07.55	10.15	02.20	BD	Tree Branch fallen on the 11KV Line at Bommarajpet Vaagu	-
11		Aliabad	Jaganguda	11KV	Medchal	01.48	03.40	01.52	BD	11KV Pole damaged at Bondala gadda	-
12		Thumkunta	Thumkunta	11KV	Medchal	02.45	04.25	01.40	BD	Tree Fallen on the 11KV Line at Thumkunta	-
13		Kolthur	Kolthur	11KV	Medchal	06.05	07.25	01.20	BD	11KV Pin Insulator Failed at Bagi Reddy Thota,Kolthur	-
14		Kandlakoya	Kandlakoya	11KV	Medchal	04.40	05.50	01.10	BD	11KV Pin Insulator failed at Pochamma Temple	-
15		Medchal	IDA Kandlakoya	11KV	Medchal	10.50	11.55	01.05	BD	CTPT Problem at Beer Company	-
16		Gowdavelly	IDA Gowdawelly	11KV	Medchal	02.30	03.30	01.00	BD	Tree Fallen on 11KV Line at Saket Vencher	-
1		Uppal Kalsa	Shanthi nagar	11KV	Habsiguda	23.20	01.00	01.40		11KV Pin insulator failed at dwarakamai Appt Vijaypuri colony	-
2		Street no 8	ISI	11KV	Habsiguda	02.56	03.46	00.50		Tree branches fallen on 11kv line at Malathi appt st no 3	-
3		Mallapur	Bhavani nagar	11KV	Habsiguda	02.30	04.35	02.05		Pin INSulator failed at Beerappagadda & Lighting arrestar fail in ss yard	-
4		Nacharam Indore	Ram Reddy nagar	11KV	Habsiguda	03.51	04.56	01.05		Tree fallen on 11kv line at ESI Hospital	-
5		NGRI	Habsiguda	11KV	Habsiguda	03.11	05.40	02.29		11KV Disk failed at street no 7 & Endkit jumper cut at Genpact	-
6		Techpark	Srikrishna	11KV	Habsiguda	03.18	04.04	00.46		Tripped on EL Due to 11KV Insulator failed near Mahapragna company	-
7		Uppal Bhagath	Saraswathi nagar	11KV	Habsiguda	02.21	03.21	01.00		11KV Insulator failed at Shilparamam	-
8		Uppal	Boduppal	11KV	Habsiguda	05.00	08.30	03.30		Tree fallen on 11kv line at Uppal Masjid & Insulator fail at SSK hospital	-
9		Nacharam Indore	Vyjyanthi	11KV	Habsiguda	21.35	22.17	00.42		11KV Pin insulator failed near Rathnanidhi Aparment at Reliance Street	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
10	RR E	NGRI	Scientist Colony	11KV	Habsiguda	22.10	01.55	03.45		11KV Pin insulator failed near pokaraju Tower beside and 11KV Habsiguda feeder load normalised and 11KV Jumper opened at Krishna Hotel	-
11		IDA Uppal	Ferrocast	11KV	Habsiguda	23.09	03.20	04.11		11KV Disk failed at near Indore cast Company	-
12		Moula-Ali	Meerpet	11KV	Sainikpuri	00.30	01.53	01.23		11KV Disk failed at Tirumal Nagar colony near Pochamma Temple (Artisian Narshmia Reddy)	-
13		Sainikpuri	Defencey Colony	11KV	Sainikpuri	09.25	11.05	01.40		11Kv Disk failed & jumper cut at Defence Colony (LM Chandu)	-
14		Kushaiguda	Kamala Nagar	11KV	Sainikpuri	02.55	03.50	00.55		11Kv Pin Insulator failed at Bata Show Room (AE)	-
15		VP Nagar	LV-II	11KV	Sainikpuri	22.30	00.07	01.37		RK Puram feeder breaker incoming Ab Switch R-Phase Post off Insulator failed & replacement at SS Yard	-
16		Malkajgiri	Bavani Nagar	11KV	Sainikpuri	23.10	00.44	01.34		11Kv Disk failed at Goutham Nagar Railway Track	-
1		HYD N	Bowenpally	Pipe Line Road	11KV	VI	00.55	02.35	01.40	EL	Tree branches fallen on lines at Bala Nagar Post Office
2	Road No.12		Road No.12	11KV	X	02.42	05.16	02.34	EL	Disc Insulator flash over at Renuka Chowdari Hospital	-----
3	Road No.12		Kanaka Durga	11KV	X	02.56	03.58	01.02	EL,OL-Bph	I/C Cable fault	Arranged B/F on 11KV Kalinga fdr
4	Nehru Nagar		Rezimental Bazar	11KV	V	03.30	05.20	01.50	EL,OL	Pin Insulator flash over at Apollo Hospital	-----
5	Nehru Nagar		Hari Hara Kala Bhavan	11KV	V	04.00	06.30	02.30	All Indication	RMU fault at NTPC	Arranged B/F on 11KV Rly. Reservation fdr
6	Nehru Nagar		Rezimental Bazar	11KV	V	06.10	07.10	01.00	All Indication	3Nos. Lugs burnt out at Apollo Hospital	-----
7	Clock Tower		Station Road	11KV	V	06.36	08.10	01.34	OL-Bph	DTR Lug burnt out at Prashanth Theater	-----
8	LV Prasad Marg		Road No.14	11KV	X	09.53	10.55	01.02	All Indication	No Visible Fault	Arranged B/F on 11KV Nandi Nagar feeder
9	New Bowenpally		Police Quarters	11KV	VI	10.10	11.50	01.40	EL,OL	Conductor snapped at Bala Nagar	-----
10	New Bowenpally		Chandana Hospital	11KV	VI	12.05	13.15	01.10	EL,OL	Tree branches fallen on lines at Anand Nagar Colony	-----
11	Yellareddyguda		Savera	11KV	X	13.50	15.00	01.10	EL	No Visible Fault	At 14:30Hrs partial fdr charged & Remaining fdr loads added on 11KV Stadium feeder
12	Toli Chowki		Hanuman Temple	11KV	X	22.57	00.18	01.21	EL,OL-Yph	Pin Insulator flash over at Hanuman Temple	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
13		I.D.P.L.	S.V.C.I.E.	11KV	VI	23.45	00.50	01.05	OL-Rph	CT PT problem at Plot No.54 (1No. HT service kept off)	-----
1	HYD S	Yakuhtpura	Bada Bazar	11KV	VIII	02.10	03.30	01.20	EL,OL	Twisted Lines at Bada Bazar	-
2		Teegalaguda	Housing Board Colony	11KV	VIII	03.00	04.22	01.22	OL-Rph	Pin Insulator flash over at H.B.Colony	-
3		Asmangadh	Asmangadh	11KV	VIII	03.05	04.28	01.23	EL	Tree branches fallen on lines at Bilal Masjid	-
1	HYD C	Erramanzil	Red Rose	11KV	I	01.28	03.57	02.29	EL	RMU fault at Red Rose Hotel	Arranged B/F on 11KV Vijaya Hospital fdr
2		Erramanzil	Jaffer Ali Bagh	11KV	I	01.31	03.35	02.04	EL	Pin Insulator flash over & tree branches fallen on lines at PC Villa Apts	-----
3		Z.P.Office	Anand Nagar	11KV	I	01.40	04.18	02.38	EL,OL	Pin Insulator flash over & Tree branches fallen on lines at Radha Apts	-----
4		Fever Hospital	Fever Hospital	11KV	II	02.35	04.55	02.20	EL,OL	Disc Insulator flash over at Balaji Apts	-----
5		Nampally	Red Hills	11KV	VII	02.52	03.54	01.02	A/R tripped	No Visible Fault	-----
6		Narayanguda	Chikkadpally	11KV	II	02.52	04.09	01.17	A/R tripped	No Visible Fault	-----
7		Bathkammakunta	C.E.Colony	11KV	II	06.05	07.30	01.25	EL	Tree branches fallen on lines at C.E.Colony	-----
8		Amberpet	Sanjeevaiah Nagar	11KV	II	06.45	08.05	01.20	EL,OL	Tree fallen on lines at Shivalayam	-----
9		ITI Mallepally	V.B.R.I.	11KV	VII	22.50	23.58	01.08	EL,OL	Faulty 11KV Shanthi Nagar fdr loads	-----
10		Bathkammakunta	C.E.Colony	11KV	II	22.50	00.57	02.07	EL	OH Cable fault at Pamula Basthi (3Nos. DTR's kept off)	(At 23:58Hrs partial fdr charged stood OK)
11		Amberpet	Patel Nagar	11KV	II	23.30	01.22	01.52	EL,OL	Breaker problem at SS	Arranged B/F on 11KV Prem Nagar fdr