

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	14	1	14	1	14	0	0	
	Grand Total	1082	6468	2	17	2	17	2	17	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Achampet	Amrabad	33kv	Nagarkurnool	13.50	16.25	02.35	EL	Insulator Failed near Chandra Vagu	Amrabad	-
1	RR N	132KV Medchal	33KV Bandamadaram	33kv	Medchal	11.50	16.32	04.42	BD	33KV AB Cable End Kit failed and replaced at Railway Gate, Gowdavelly	33KV Bandamadaram	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 13.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thimmannagudem	Ch.Chennaram	11KV	Nalgonda	07.43	11.00	03.17	EL	11KV Insulators Failed	-
2		Utlapally	Kalwapally	11KV	Miryalaguda	09.25	11.25	02.00	EL	Jumper Cut	-
3		Damarcherla	Wadapally	11KV	Miryalaguda	13.30	14.30	01.00	EL	Tree fallen on the Line	-
4		Pottichelma	Chalukurthy	11KV	Miryalaguda	11.30	14.20	02.50	EL	Jumper Cut	-
5		Kamareddygudem	Pusalapad	11KV	Miryalaguda	00.00	05.10	05.10	EL	Jumper Cut	-
6		Kandibanda	Kandibanda	11KV	Huzurnagar	08.04	10.24	02.20	EL	Due to 11kv Jumper Cutted	-
7		Azeempet	Kanchanpally	11KV	Bhongir	04.00	06.15	02.15	EL/OL	11kv Disc Failed Near Sub-Stations	-
1	MDK	Ismailkhanpet	Erdanoor	11KV	Sangareddy	05.35	07.35	02.00		B/D due to Pin Insulator failed	-
1	SDPT	Rangadampally	Rangadampally Agl	11KV	SDPT	10.52	11.15	00.23		B/D due to Pin Insulator failed	-
2		Thadkapally	venkatapur agl	11KV	SDPT	01.10	13.07	11.57		B/D due to 11DISK FAIL	-
3		Rajgopalpet	mundrai	11KV	SDPT	07.41	10.50	03.09		B/D TREE BRANCHES FALL ON LINE	-
4		ERRAVALLY	KCR (LC.NO:26311)	11KV	Gajwel	11:33	20:18	08.15		B/D due to CABLE CHANGE	-
5		KONDAPAK	KONDAPAK AGL (LC.NO:24301)	11KV	Gajwel	5:30	13:10	7:20		PEACOCK FELLDOWN ON THE LINE & DISK RPOBLEM	-
6		DOULTHABAD	SP BANDARAM (LC.NO:1840)	11KV	Gajwel	17.40	19.30	02.50		JUMPER OPEN	-
1	RR S	Kondapur	IDPL	11KV	Moosapet Old	13.15	14.20	01.05	EL & OL	CT/PT Problem (11KVAB switch open near Devi Hotel at Moosapet)	-
1	HYD S	Jiyaguda	Samasta Narayana	11KV	IX	01.23	02.40	01.17	EL	Brass Patti touching to Channel at Samasta Narayana	-----
2	HYD C	Zamistanpur	L.N Colony	11KV	II	14.49	19.55	05.06	EL,OL	DTR Cable fault at Hanuman Temple	Arranged B/F on 11KV Mother Dairy feeder