

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	12	1	12	1	12	0	0	
	Grand Total	1082	6468	1	19	1	19	1	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.06.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Pebbair	33KV	Wanaparthi	19.55	20.45	00.50	E/L&O/L	Due to Rain	Pebbair	Alternate Supply Arranged from 33KV Chinnamaroor at 20:45Hrs

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamangundla	A.P.Lingotam	11KV	Nalgonda	9:10	11:30	2:20	E/L	11KV Line Cut	No
2		Eduloor	Parada	11KV	Nalgonda	11.10	14.40	03.30	E/L	11KV Line Jumper Cut	No
3		Palem	Ogodu	11KV	Nalgonda	10.50	13.00	03.50	E/L	HT/LT Melting SS-6	No
4		Koppole(K)	Bheemavaram	11KV	Nalgonda	11.45	15.00	05.45	O/L	Heavy Gale and Tree branches fallen on the line and AB Switch femail Cut	No
5		Jalapuram	Gottiparthi	11KV	Suryapet	08.30	11.00	02.30	E/L	11KV Insulator flashover	No
6		IDA	Bommaipally	11KV	Bhongir	04.00	10.40	06.40	EL/OL	11KV Line snapped near Bommaipally (V)	No
7		Manaikunta	Veldevi	11KV	Bhongir	02.10	09.20	07.10	EL/OL	16KVA DTR failed near Veldevi (V)	No
8		Suddala	Pallepahad	11KV	Bhongir	08.10	09.35	01.25	EL/OL	100KVA DTR failed at Subburi. Shankaraiah well near Pallepahad (V)	No
9		Malkapur	Malkapur Agl	11KV	Choutuppal	13:22	15:30	2:08	EL/OL	11KV Line snapped near Malkapur (V)	No
1	SDPT	Chittapur	Chowder Pally	11KV	Siddipet	07:30	08:40	1:10		Due to wind	No
2		Erravally	Erravally	11KV	Gajwel	11:54	12:38	00.44		Disc failed	No
3		Gowraram	Town 2	11KV	Gajwel	15:00	16:30	01.30		11KV Line phase to phase	No
1	RR N	Yellampet	Yellampet Agl	11KV	Medchal	10:55	12:45	1:50		11KV Line cut and replaced at Yellampet 'X' Road	No
1	RR E	IDA Uppal	Metro	11KV	Habsiguda	15:22	16:48	1:26		CT failed at SS Yard	B/F from 11KV Srikrishna feeder
2		RGK	Barsipet	11KV	Sainikpuri	09.40	10.25	00.45		11KV Disc insulator failed at Venrag Colony	No
1	HYD N	Gymkhana	Rani Bagh	11KV	C-VI	00.05	01.50	01.45	EL,OL-Bph	HT Line snapped at Lorry Adda	No
2		Chinna Thokatta	Old Bowenpally	11KV	VI	9:46	10:49	1:03	EL,OL-Bph	No Visible Fault	No
3		Macha Bollaram	Balaji Rice Mills	11KV	C-VI	21:24	22:28	1:04	EL	Pin Insulator flash over at Anjanapuri Colony	No
1	HYD C	Toli Chowki	Hakimsha	11KV	VII	15.45	16.50	01.05	EL,OL	Relay problem at SS	Arranged B/F on 11KV Paramount Hills fdr