

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		3		3		3			
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		5		5		5			
	Total	606	3055	0	14	0	14	0	14	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		4		4				
2	NLG	144	988		16		16		16			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	17	4	17	4	17	0	0	
	Grand Total	1082	6468	4	31	4	31	4	31	0	0	

## Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/132KV SS Palkonda	Kodur	33KV	Mahabubnagar	06.58	09.19	07.33	E/L	Insulator Fallen Down & Touched to the Tower at Bandamidapally		Alternate Supply Arranged From 132KV SS Mahabubnagar to 33KV Machanpally Feeder at 7:33Hrs.
2		Makthal	Narwa	33KV	Narayanapet	19.50	20.00	00.10	E/L	Due to Rain		Alternate Supply Arranged 132KV Marikal to 33KV Eklaspur at 20:00Hrs.
3		Maddur	Pallerla	33KV	Narayanapet	19.30	22.20	02.50	E/L	Jumper Cut at 132KV SS Maddur		Alternate Supply Arranged From 33KV Maddur at 22:05Hrs.
4		Nagarkurnool	Rakonda	33KV	Nagarkurnool	17.46	18.00	00.14	E/L&O/L	Due to Rain		Alternate Supply Arranged form 132KV Achampet to 33 KV Achampet at 18:00Hrs.

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 17.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Bollepally	Jampally	11KV	Bhongir	05.00	09.30	04.30	EL/OL	11kv disc failed near Jampally (v)	-
2		Alair	Ikkurthy	11KV	Bhongir	03.00	07.00	04.00	EL/OL	11kv Insulator failed near Ikkurthy (v)	
3		Panthangi	Panthangi Agl	11KV	Choutuppal	03.30	08.10	04.40	EL/OL	11kv Line snapped near Reddybavi (v)	
4		Athmakur(S)	Dacharam	11KV	Suryapet	03.30	06.18	02.48	E/L	11Kv Jumper cut	
5		Penpahad	Dubbathanda	11KV	Suryapet	13.10	16.00	02.50	E/L	11Kv Insulator failed	
6		Munagala	Munagala(T)	11KV	Huzurnagar	07.20	09.15	01.55	E/L	11kv Disk Failure	
7		Chervugattu	Gummalabavi	11KV	Nalgonda	06.10	13.00	06.50	E/L	11KV Jumper cut	
8		Nakkalapally	Shapally	11KV	Nalgonda	05.45	09.10	03.25	E/L	11KV Insulators failed	
9		Narketpally	M.Yedavally	11KV	Nalgonda	00.10	06.50	06.40	E/L	11KV Jumper cut	
10		Aitipamula	R.C.Puram	11KV	Nalgonda	04.05	08.06	04.01	O/L	Thatimatta fallen on 11KV line	-
11		Aitipamula	Gangadevigudem	11KV	Nalgonda	04.15	06.45	02.30	O/L	11KV Jumper cut	-
12		Kattangur	Bollepally	11KV	Nalgonda	00.25	09.10	08.45	E/L	11KV Insulators blast	-
13		Kattangur	Dugenelly	11KV	Nalgonda	05.00	07.00	02.00	E/L	Thatimatta fallen on 11KV line	-
14		Palem	Palem	11KV	Nalgonda	04.00	10.50	06.50	E/L	11KV line cut at Palem village	-
15		P.D. Pally	Tripuraram	11KV	Miryalguda	14.53	16.55	02.02	E/L	11KV Insulators failed	-
16		Bugathanda	kasarajpally	11KV	Devarakonda	14.10	14.45	00.35	E/L	11KV Jumaper Cut	-
1	MDK	Gummadidala	Mambapur	11KV	Patancheru	02.00	08.55	06.55		B/D due to Jumper cut	-
1	RR S	ESCI	Divya Sree	11KV	Gachibowli	10.25	15.00	04.35		CTPT spark in Divya Sree (GCB Phase cut)	-
2		IIIT	APHB Colony	11KV	Gachibowli	10.51	11.56	01.05		11kv Insulator failed at Med plus, APHB Colonu	-
3		SEZ	Swaroop Chand Kotari	11KV	Kondapur	12.35	20.05	07.30		Cable endy kit fai;ed in Swaroop Chand Kotari	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	JPTL	PJR Enclave	11KV	Kukatpally	11.45	14.00	02.15	EL	11kv Insulator failure, Delhi public school disk insulator failure & a bird fallen on the 11kv line near Padmavathi Aptt	-
2		Medchal	CMR	11KV	Medchal	03.30	04.35	01.05	EL	11KV Jumper Cut & Replaced at HP Petrol Bunk	-
3		Athiwelly	Somaram	11KV	Medchal	12.55	15.20	02.25	EL/OL	11KV Pole damaged by Lorry at Dongalagutta Thanda	-
4		Shameerpet	Anthaipally	11KV	Medchal	17.30	19.30	02.00	EL	11KV Pin Insulator failed at Anthaipally Village	-
5		Town Medchal	Country Club	11KV	Medchal	20.40	21.48	01.08	EL	Tree fallen on the 11KV Line at MRO Office	-
1	RR E	Rampally Dayara	Vanneguda AGL	11KV	Keesara	18.32	20.10	01.38		11KV 3Nos Pole damaged near Manyam Engineering Company	-
1	HYD N	I.D.P.L.	Wonder Plast	11KV	Bowenpally	11.20	12.35	01.15	EL,OL-Bph	Pin Insulator flash over at Plot No.34, Bala Nagar	-
1	HYD S	Falaknuma	Aliyabad	11KV	Charminar	04.15	06.08	01.53	EL,OL-Bph	Faulty 2Nos. DTR's at Aliyabad	Partial fdr charged & remaining loads added on 11KV Roopalal Bazar fdr
1	HYD C	Bathkamma Kunta	Ayyappa Temple	11KV	Azamabad	00.07	01.15	01.08	EL,OL	Tree branches fallen on lines at Telephone Exchange	-
2		Vittalwadi	Y.M.C.A	11KV	Azamabad	14.10	15.30	01.20	EL,OL-Rph	Pin Insulator flash over & Tree branches fallen on lines at Iqbal Tower	-
3		Asif Nagar	N.S.F Colony	11KV	Mehdipatanam	15.35	18.02	02.27	EL	5way RMU Cable fault at Hari Babu Hotel	(17:10 Hrs) partial fdr charged