

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		3		3		3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT				10		10		10			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>18</b>	<b>0</b>	<b>18</b>	<b>0</b>	<b>18</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>23</b>	<b>0</b>	<b>23</b>	<b>0</b>	<b>23</b>	<b>0</b>	<b>0</b>	



TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 19.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kattangur	Bollepally	11KV	Nalgonda	02.00	05.00	03.00	EL	11 KV Line Jumper Cut	-
2		Mukundapuram	Chandupatla	11KV	Suryapet	10.30	14.10	03.40	E/L	Conductor snapped	-
3		Dhopahad	New Banjarahills	11KV	Suryapet	11.50	13.30	01.40	E/L	Insulator failed	-
4		Urulugonda	Thummagudem	11KV	Huzurnagar	04.30	07.30	03.00	EL	Due to tree branch fall on 11kv line	-
5		Maryala	Maryala town	11KV	Bhongir	04.00	07.50	03.50	EL/OL	11 kv Disc failed near Sub station 11 th pole Maryala town	-
6		Datherpally	Jangamapally	11KV	Bhongir	03.00	08.41	05.41	EL/OL	11 kv Line snapped near Thalla gadda & LT Line snapped near Datherpally village	-
7		Arror	Lingarajupally	11KV	Choutuppal	05.20	06.20	01.00	EL/OL	11 kv Line snapped near Lingarajupally village	-
1	MDK	Patancheru Town	Allwyn	11KV	Patancheru	03.00	05.10	02.10		BD due to Insulator failed	-
1	SDP	Chinnagudavally	Rampur	11KV	Siddipet	19.20	23.45	04.25		B/D for for Male, Female fail	-
2		Jakkapur	Shanigakunta	11KV	Siddipet	05.49	13.54	08.05		B/D for 11 KV Insulater fail LC No.24062	-
3		Thimmapur	Thimmapur	11KV	Siddipet	07.33	07.57	00.24		B/D for Disk fail LC No.35847	-
4		Thimmapur	Padmanbapally	11KV	Siddipet	07.33	07.57	00.24		B/D for Disk fail LC No.35847	-
5		Dharmajipet	Egundaswamy	11KV	Siddipet	02.00	07.56	05.56		B/D for Tree fall at 11KV Line	-
6		Mirdoddy	Andhey	11KV	Siddipet	13.11	23.30	10.19		B/D	-
7		Vittalapur	Rangaipally	11KV	Siddipet	07.40	09.10	01.30		B/D for 11KV Indulater fail LC No.16139	-
8		Gurjakunta	Vecharani	11KV	Husnabad	07.45	09.45	02.00		Poles Break	-
9		Gurjakunta	Dhommata	11KV	Husnabad	11.50	12.45	00.55		Poles Break	-
10		Akunoor	Rudraipally	11KV	Husnabad	02.30	09.15	06.45		Break down	-
1	RR E	Narapally	Prathap Singaram	11KV	Keesara	13.40	14.40	01.00		11KV Copper patti cut near Vaibhav Green Homes at Maktha	-
2		Nagaram	P S Rao Nagar	11KV	Keesara	23.53	02.37	02.44		11KV Line cut near I-Comm Company & B/F from 11KV Dammaiguda feeder	-
1	HYD N	Hakimpet	Risala Bazar	11KV	C-VI	21.32	22.40	01.08	All Indication	No Visible Fault	-
1	HYD S	Attapur	Allah Masjid	11KV	III	04.05	06.00	01.55	EL,OL	Conductor snapped at Konda Reddy Guda	Arranged B/F on 11KV Kishanbagh feeder
1	HYD C	Chilkaiguda	Golconda X Roads	11KV	II	03.15	04.22	01.07	EL,OL-Bph	No Visible Fault	Arranged B/F on 11KV Dayara Market feeder