

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT			2	5	2	5	2	5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>13</b>	<b>3</b>	<b>13</b>	<b>3</b>	<b>13</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>16</b>	<b>3</b>	<b>16</b>	<b>3</b>	<b>16</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 20.06.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Rajapur	33kv	Jadcherla	09.58	10.45	00.47	E/L & O/L	CT stude Melt & Oil leakage at 132KV Balanagar	Rajapur	-
1	SDPT	Gajwel	B V Pur	33kv	Gajwel	17.55	20.45	02.50		BD( Havey Rain Insulators Failed)	B V Pur	-
2		Gajwel	Mulugu	33kv	Gajwel	21.15	21.20	00.05		BD(Alternate Supply 33 Kv Feeder Wardarajpur)	Mulugu	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 20.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Thirmalapur	Dondlapally	11kv	Jadcherla	12.04	13.24	01.20		11 KV Insulater Fail Near Raghavapur (v).	-
2		Peddarevelly	Bodagutta	11kv	Jadcherla	04.10	09.20	05.10		11 KV Wire Cut Near Devuni gutta thanda.	-
1	NLG	Ravulapally	Ravulapally	11kv	Suryapet	12.20	15.40	03.20	E/L	11Kv Jumper cut	-
2		Dirsincherla	Somaram	11kv	Huzurnagar	06.00	07.45	01.45	E/L	11KV Line Snapped	-
3		Siripuram	Srirangapuram	11kv	Huzurnagar	11.00	12.25	01.25	E/L	11Kv Jumper cut	-
4		Choutuppal	Jubkapally	11kv	Choutuppal	13.05	15.15	02.10	EL/OL	11kv Insulator Failed near Jublakpally (V)	-
5		Palem	Ogodu	11kv	Nalgonda	11.50	13.10	01.20	E/L	11KV Line Jumper Cut	-
6		Edulur	Parada	11kv	Nalgonda	08.40	10.20	01.40	E/L	11Kv Insulator Failed	-
1	SDPT	Pandilla	Kunchanpally	11kv	Husnabad	16.30	17.30	01.00		LT/HT, same rectified	-
2		Koheda	Sriramulapally	11kv	Husnabad	10.05	12.00	01.55		Insulator failure, same rectified	-
3		Venkateshwarapally	Venkateshwarapally	11kv	Husnabad	11.10	14.00	02.50		AB switch failure, same rectified	-
4		Gandipally	Ramavaram	11kv	Husnabad	17.30	23.50	06.20		BD due to rain	-
5		Ramchandrapur	Vinjalpally	11kv	Husnabad	15.10	17.30	02.20		LT/HT, same rectified	-
1	RR S	Papireddy Colony	Papireddy Colony	11kv	Gachibowli	15.17	16.17	01.00	BD	11KV Jumper cut and 11KV line cut at Papireddy forest area.	-
1	RR N	Bandamadaram	Rock Sand	11kv	Medchal	09.15	11.05	01.50	BD	HT/LT Line melted at Vijay Rami Reddy Thota	-
1	RR E	Yadgarpally	Cheryala	11kv	Habsiguda	13.50	14.30	00.40		Cameleon fallen on 11kv line at Petrol bunk	-