

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				8		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	15	3	15	3	15	0	0	
	Grand Total	1082	6468	3	19	3	19	3	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.06.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanapet	00.45	01.25	00.40	EL	Tree follen on the line		NO
2		Balanagar	Kollur	33KV	Jadcherla	23.50	00.50	01.00	EL	Tree branch follen on the line		NO
1	MDK	Jogipet	G.Peddapur	33KV	Jogipet	11.35	15.35	04.00		BD due to insulator Failed		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 23.06.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Dirsenapally	Alugunur	11KV	Suryapeta	12.30	15.10	02.40	E/L	Insulator Flashover	-
2		Karivirala	Keshavapuram	11KV	Huzurnagar	05.00	08.00	03.00	EL	Due 11kv line Snapped	-
3		Velgupally	Velgupally	11KV	Nalgonda	07.40	09.55	02.15	EL	SS-3 Insulator Failed	-
4		Panagal	Panagal Town	11KV	Nalgonda	09.13	10.30	01.17	EL	Sqaurill (Vudtha) Fallen on HG Fuse Under SS-14	-
5		Nidamanoor	Nidamanoor	11KV	Miryalaguda	08.30	11.15	02.45	EL	11KV Conductor Snapped	-
6		Panthangi	Panthangi Agl	11KV	Choutuppal	06.24	08.18	01.54	EL	63 kva DTR Failed at SS- 2 near Panthangi village	-
1	MDK	EPIP-III	Vilas Polymer	11KV	Sangareddy	00.00	05.00	05.00		BD Due to Jumper cut	-
1	SDPT	Thornala	Thornala	11KV	Siddipet	17.50	19.18	01.28		B/D-Tree bunches fallen on 11KV line-Rectified	-
2		Kammarlapally	Kothapally	11KV	Siddipet	12.35	14.30	01.55		B/D-11KV jumper cut-Rectified	-
3		Thimmapur	Padmanabhunipally	11KV	Siddipet	17.50	19.06	01.16		B/D-11KV disk fail-Rectified	-
4		Habsipur	Dharmaram	11KV	Siddipet	01.20	06.00	04.40		B/D-11KV jumper cut-Rectified	-
5		Thigul	Thigul AGL	11KV	Gajwel	10.55	11.59	01.04		BD (DTR CABLE MELT)	-
6		Gowraram	Pathur Feeder	11KV	Gajwel	15:00	16:00	01.00		BD (Tree fallen)	-
7		Husnabad	Husnabad Town-2	11KV	Husnabad	09.15	09.25	00.10		Bird Fallen on Line	-
8		Pandilla	Pandilla Express	11KV	Husnabad	10.30	11.00	00.30		Pin Insulator Fail	-
1	RR N	Jeedimetla SS II	Kompally pharma	11KV	Jeedimetla	11.40	12.50	01.10	BD	11kv jumper cut & fallen on the channal at Phase III	-
1	RR E	Aushapur	Aushapur	11KV	Keesara	09.40	10.40	01.00		Squarrel fallen on 11KV line at Srinidhi Resorts	-
1	HYD N	MLA Colony	Lotus Pond	11KV	Banjarahills	01.40	03.00	01.20	EL,OL-Bph	Cable End Kit failed at Plot No.3, Lotus Pond	-
1	HYD C	Mothi Mahal	M.D.Lines	11KV	Mehdipatnam	08.40	10.22	01.42	EL,OL-R&Yph	Pin Insulator flash over at M.D.Lines	-