

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	6	5	6	5	6			
2	NLG	144	988	3	16	3	16	3	16			
3	MDK	107	933	1	3	1	3	1	3			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	9	29	9	29	9	29	0	0	
	Grand Total	1082	6468	9	34	9	34	9	34	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.05.2020

## Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/132KV SS Palkonda	Janampet	33KV	Mahabubnagar	05.25	08.46	03.21	E/L	Insulator Failed at Sher Pally Gate	Janampet	-
2		Balanagar	Rajapur	33KV	Jadcherla	06.40	08.55	02.15	E/L	Tree follen on the line at Khanapur(V)	Rajapur	-
3		Balanagar	Rajapur	33KV	Jadcherla	14.45	15.35	00.50	E/L	B Phase CT Oil leackage stude melt	Rajapur	Altrenate Supply Arranged to 33KV Balanagar feeder at 15:35Hrs
4		leeza	Mitta Doddy	33KV	Gadwal	03.33	05.58	02.25	E/L	Tree Fallen on the Line	Mitta Doddy	Altrenate Supply Arranged to 33KV Gattu feeder at 5:10Hrs
5		220/33KV SS Singotam	Narsaipally	33KV	Nagarkurnool	04.58	10.26	05.28	E/L	Tree branches follen on the line	Narsaipally	-
1	NLG	Wadapally	Janpahad	33KV	Miryalguda	01.05	05.00	03.55	E/L	33KV Insulator failed	Janpahad	-
2		Suryapet	Kethapally	33KV	Suryapet	11.35	15.00	03.25	EL/OL	Snake fallen on the 33Kv Insulator	Kethapally	-
3		Ramapuram	Mellacheruvu	33KV	Huzurnagar	04.30	08.40	04.10	EL/OL	33KV Insulator failed	Mellacheruvu	-
1	MDK	Kandi	HFC-II	33KV	Sangareddy	16.40	18.30	01.50		BD due to Tree branches fallen on line	HFC-II	-

## Circle-wise 11KV Breakdowns

Date: 30.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Burgupally	11KV	Jadcherla	06.45	08.41	01.56		11KV Insulator fail near Sudhaikunta thanda	-
2		Hemajipur	Hemajipur	11KV	Jadcherla	07.10	10.00	02.50		11KV Jumper cut near Hemajipur	-
3		Marrikal	Chakalapally	11KV	Jadcherla	06.20	10.50	04.30		Tree follon the line near Chakalapally	-
4		Lokirew	Lingampally	11KV	Jadcherla	08.51	09.49	00.58		11KV Insulator fail near Lingampally	-
5		Nawabpet	Lokirew	11KV	Jadcherla	09.00	11.00	02.00		11KV Insulator fail near Lokirew	-
6		Karkonda	Karkonda	11KV	Jadcherla	07.00	11.10	04.10		11KV Wire cut near Karkonda	-
1	NLG	Indugula	Indugula	11KV	Nalgonda	01.00	07.30	06.30	E/L	SS-26 Insulator Failed	-
2		Thurkapally	Thurkapally	11KV	Nalgonda	07.30	10.12	02.42	E/L	11 KV Jumper Cut	-
3		Nemmani	Merlakunta	11KV	Nalgonda	00.00	06.50	06.50	E/L	11 KV Insulator Failed	-
4		Thimmanagudem	Ch.Chennaram	11KV	Nalgonda	09.50	12.26	02.36	E/L	11 KV Jumper Cut	-
5		Palem	Bopparam	11KV	Nalgonda	09.10	12.00	02.50	E/L	Tree Fallen on 11 KV Line	-
6		Miryalguda Town	Ashoknagar	11KV	Miryalguda	02.00	05.00	03.00	E/L	11KV pole damaged	-
7		Miryalguda Town	Indl	11KV	Miryalguda	03.00	07.00	04.00	E/L	11KV pin insulator failed	-
8		Kothagudem	Kothagudem	11KV	Miryalguda	03.30	09.30	06.00	E/L	11KV conductor snapped	-
9		B.Annaram	B.Annaram	11KV	Miryalguda	04.00	09.30	05.30	E/L	11KV jumper cut near SS	-
10		A.D.Pally	Wadappally	11KV	Miryalguda	05.20	06.40	01.20	E/L	11KV pin insulator failed	-
11		A.D.Pally	T.v.Gudem,	11KV	Miryalguda	03.50	05.35	01.45	E/L	11KV conductor snapped	-
12		Thungathurthy	Ganugubanda	11KV	Suryapet	07.00	10.49	03.49	E/L	11Kv Line melt	-
13		Jalalpuram	Gottiparthi	11KV	Suryapet	05.00	08.00	03.00	E/L	11Kv Insulator failed	-
14		Kalmalcheruvu	Kalmalcheruvu	11KV	Huzurnagar	06.00	07.15	01.15	E/L	11KV conductor snapped	-
15		Mukundapuram	Kalluru	11KV	Huzurnagar	06.15	08.30	02.15	E/L	11KV jumper cut	-
16		Athmakur	Rahimkhanpet	11KV	Bhongir	02.30	06.45	04.15	EL/OL	11 kv Insultaor failed at Sarpanch well near Rahimkhanpet village.	-
1	MDK	EPIP-I	Chitrakoot	11KV	Sangareddy	16.05	19.10	03.05		BD due to Insulator & Disk failed	-
2		EPIP-III	Vilas Polymer	11KV	Sangareddy	16.00	17.00	01.00		BD due to After petrolling no fault found	-
3		Pati	My Home	11KV	Patancheru	15.20	16.25	01.05		BD due to Tree fallen on line	-
1	SDP	Akbarpet	Bhoompally	11KV	Siddipet	02.45	05.46	03.01		B/D ( Kv Wire cut )	-
2		THIGUL	THIGUL AGL LC.NO:6863	11KV	Gajwel	15.30	16.52	01.22		11KV DISC FAIL	-
3		WARDARAJPUR	SHIVAR VENKATAPUR LC.NO:25097	11KV	Gajwel	23.03	10.15	11.12		DISC FAIL	-
4		Bejjanki	Kallepally	11KV	Husnabad	12.10	18.10	06.00		Insulator Fail	-
1	RR S	Gachibowli	Aparna	11KV	Gachibowli	07.35	08.35	01.00		No Visible Fault (Backfeeding From 11Kv Gopanpally)	-
1	RR N	Kompally	Kompally	11KV	Medchal	16.58	18.03	01.05	BD	11KV Pin Insulator Failed and replaced at Subiksha Godham	-
2		Yellampet	IDA Yellampet	11KV	Medchal	16.50	18.40	01.50	BD	11KV Pin Insulator Failed and replaced at Navabharath Company	-
1	HYD S	Miralam	Hasan Nagar	11KV	III	10.05	11.30	01.25	EL	Cable fault at Hasan Nagar	Arranged B/F on 11KV Madina Masjid feeder
1	HYD C	Indira Park	Ambedkar Nagar	11KV	I	08.00	09.52	01.52	EL,OL-Rph	Tree branches fallen on lines at NTR Stadium	-