

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1	1	1	1	1	1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	3	5	3	5	3			
2	NLG	144	988									
3	MDK	107	933		2		2		2			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>5</b>	<b>6</b>	<b>5</b>	<b>6</b>	<b>5</b>	<b>6</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>6</b>	<b>9</b>	<b>6</b>	<b>9</b>	<b>6</b>	<b>9</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 02.03.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SVS Eidra	33KV	Mahabubnagar	05.30	06.10	00.40	E/L	No Visible fault	SVS Eidra	Diverting SVS Yedira Loads From 33KV Jadcherla
2		220/132KVSS Palkonda	Bhoothpur	33KV	Mahabubnagar	03.50	06.59	03.09	E/L & O/L	No Visible fault	Bhoothpur	-
3		Kodangal	Hamsanpally	33KV	Vikarabad	03.10	03.25	00.15	E/L	Line Isolator Opened Supply Stood OK	Hamsanpally	-
4		Nagarkurnool	Rakonda	33KV	Nagarkurnool	12.48	16.00	03.12	E/L	33KV Disc failed and replaced near Sarswathi Temple	Rakonda	-
5		Balanagar	Chinchode	33KV	Shadnagar	17.20	18.35	01.15	EL	33KV Line cut out near Vityal SS	Chinchode	-
1	HYD C	132KV Asif Nagar	A.S.R.Raju Nagar	33KV	Asif Ngr	14.18	14.30	00.12	EL,OL-Rph	Cable dig by unknown person	A.S.R.Raju Nagar	Loads transferred onto 132KV Imlibun SS via 33KV Seetharambagh SS

## TSSPDCL - LMRC / Corporate office

Date: 02.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marrikal	Chakalapally	11KV	Jadcherla	04.00	08.10	04.10		11KV Wire cut near Chakalapally	-
2		Kothamolgara	Karvena	11KV	Jadcherla	04.10	08.20	04.10		11KV Insulator fail near Kothamolgara	-
3		Kothamolgara	Madigatla	11KV	Jadcherla	04.20	08.40	04.20		11KV Jumper cut near Nallagutta	-
1	MDK	EPIP-II	Padmapower	11KV	Sangareddy	04.10	07.00	02.50		BD due to Jumper cut	-
2		SOL	BMF	11KV	Patancheru	03.10	04.00	00.50		BD due to Jumper cut	-
1	SDP	Husnabad	Pandilla	11KV	Husnabad	00.00	08.05	08.05		Line Snapped	-
1	RR N	ICICI	Bharath Bio Tech	11KV	Medchal	08.40	10.20	01.40	EL/OL	Tree Fallen on the 11KV Line at Semi Labs(11KV Line AB Switch Opened)	-
1	RR E	CRPF	CRPF Non Residential	11KV	Habsiguda	08.35	13.05	04.30		11KV HG Fuse Insulator failed at CRPF Main Road	-
1	HYD C	Bathkammakunta	Ahobilmutt	11KV	II	13.37	15.37	02.00	OL-Rph	Jumper cut & Auto Reclosure problem at Hotel Management	-