

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	3	2	3	2	3	0	0	
	Grand Total	1082	6468	2	8	2	8	2	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.03.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Haliya	Rajavaram	33KV	Miryalguda	17:15	18:10	0:55	E/L	33KV Jumper cut	Rajavaram	No
1	MDK	Gummadidala	GPSS-2	33KV	Patancheru	10:45	12:00	1:15		Conductor snapped at Domadugu village	GPSS-2	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Angadipeta	Chilkamarri	11KV	Devarakonda	5:02	16:30	11:28	E/L	220 KV Line earth wire cut and fallen on 11KV line	No
2		Dugayala	Dugayala	11KV	Devarakonda	08.20	10.00	01.40	E/L	11KV Insulator failed & 11 KV line cut	No
3		Nampally	Peddapuram	11KV	Devarakonda	04.45	09.45	05.00	E/L	Tree fallen on the 11KV line	No
1	RR N	Medchal	IDA Kandlakoya	11KV	Medchal	18:40	19:30	0:50		11KV Disc failed and replaced at Post Chemical company	No
2		Ravalkole	Ravalkole	11KV	Medchal	17.54	19.11	01.17		Tree fallen on 11KV line at Ravalkole Village	No
1	RR E	Sainikpuri	Saipuri	11KV	Habsiguda	11:55	12:30	0:35		GI Wire fallen on 11KV line at Saipuri Colony	No
2		Narapally	Apmeet	11KV	Habsiguda	03.50	04.30	00.40		Pin insulaotr failed at Devya nagar	No
1	HYD S	Ch' Baradari	Fire Station	11KV	III	07.50	09.14	01.24	EL,OL	Conductor snapped at Fire Station backside (Lorry dash to Pole)	No