

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	3	2	3	2	3	0	0	
	Grand Total	1082	6468	2	5	2	5	2	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.03.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1		Achampet	Veltoor	33KV	Nagarkurnool	15.15	16.55	01.40	EL	Pin binding failed near Tadoor		No
2	MBNR	Wanaparthi	Solipur	33KV	Wanaparthi	16.17	17.15	00.58	OL&EL	33KV Conductor snapped	Solipur	Alternate supply arraged from 132KV SS Ghanpur- 33KV Solipur feeder at 17:15Hrs.

TSSPDCL - LMRC / Corporate office

Date: 17.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Penpahad	Anajipuram	11KV	Suryapet	11:30	14:00	2:30	EL	Conductor snapped	No
2		Garidepally	Kalamacheruvu	11KV	Huzurnagar	06.40	08.15	01.35	EL	11KV Jumper cut	No
3		Burugadda	Gopalapuram	11KV	Huzurnagar	14.20	16.25	02.05	EL	11KV Line snapped	No
1	RR N	Kompally	Apama	11KV	Medchal	21:45	22:28	0:43		11KV Pole damaged by the Lorry at Fish Godown	No
1	HYD N	Chilkaiguda	Dandu Pentaiah	11KV	V	11.48	13.20	01.32	EL,OL-R&Yph	3 Way RMU problem at Dandu Pentaiah	Arranged B/F on 11KV MCH Park fdr