

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	4	29	4	29	4	29			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>7</b>	<b>29</b>	<b>7</b>	<b>29</b>	<b>7</b>	<b>29</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>7</b>	<b>33</b>	<b>7</b>	<b>33</b>	<b>7</b>	<b>33</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 20.03.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/132KV SS Palkonda	Bhoothpur	33kv	Mahabubnagar	07.08	09.27	02.19	E/L	Insulator Failed near Sidhaiapally Road	Bhoothpur	-
2		Kalwakurthy	SLC Mills-1	33kv	Nagarkurnool	12.36	20.40	08.04		Due to CT Failed	SLC Mills-1	-
1	NLG	Madugulapally	Laxmidevigudem	33kv	Miryalaguda	07.05	10.10	03.05	EL	33KV conductor melt and Jumper cut due to heavy rain and gale	Laxmidevigudem	-
2		220KV Miryalaguda	Tripuraram	33kv	Miryalaguda	07.22	11.30	04.08	EL	33KV Pin Insulator failed due to heavy rain and gale	Tripuraram	-
3		Suryapet	Nemmikal	33kv	Suryapet	06.00	10.40	04.40	EL	3Nos Insulators flashover	Nemmikal	-
4		Suryapet	Chandupatla	33kv	Huzurnagar	22.15	08.30	10.15	EL	33 KV INSLATER FAILED	Chandupatla	-
1	MDK	Sadasivpet	Jogipet	33kv	Sangareddy	00.40	01.30	00.50		B/D Due to Jumper Cut	Jogipet	-

## TSSPDCL - LMRC / Corporate office

Date: 20.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Indugula	Malaparajugudem	11kv	Nalgonda	13.00	14.00	01.00	EL	Jumper cut	-
2		Pamangundla	Ismailpally	11kv	Nalgonda	12.00	13.05	01.05	EL	Insulator failed	-
3		Jammigadda	Kesaram	11kv	Suryapet	06.00	08.00	02.00	EL	Jumper cut	
4		R.C Puram	R.C Puram	11kv	Suryapet	06.30	09.00	02.30	EL	Disk flashover	
5		G.T Giri	Thirumalagiri	11kv	Suryapet	06.00	09.10	03.10	EL	Insulator flashover	
6		Thatipamula	Sri ram thanda	11kv	Suryapet	08.30	11.00	02.30	EL	Insulator flashover	
7		Nagaram	D.Kothapally	11kv	Suryapet	11.30	13.35	02.05	EL	Jumper cut	
8		Thugnathurthy	B. Ramaram	11kv	Suryapet	10.00	13.27	03.27	EL	Conductor snapped	
9		Alingapuram	Raghavapuram	11kv	Huzurnagar	05.00	06.30	01.30	EL	11 KV LINE SNAPPED	
10		Munagala	Barakathgudem	11kv	Huzurnagar	03.00	05.45	01.45	EL	11 KV LINE SNAPPED	
11		Mothey	Town	11kv	Huzurnagar	05.00	07.00	02.00	EL	11 KVJUMPER CUT	
12		Bibinagar	Hindusthan indl	11kv	Bhongir	05.00	08.10	03.10	EL	11 kv Disc failed & HT/LT	
13		Kondamadugu	Nemaragommula	11kv	Bhongir	04.00	08.50	04.50	EL	Solid core Insulator failed at Sai baba temple Kondamadugu Village. 3 phase B/d single phase ok	
14		Patelgudem	Gundlagudem	11kv	Bhongir	20.05	21.15	01.10	EL	15 kva dtr failed at CSI School Near Gundlagudem village	
15		Chada	Kateypaly	11kv	Bhongir	14.00	16.30	02.30	EL	11kv Line snapped near Kateypally Village	
16		Chada	Chada Indl	11kv	Bhongir	17.00	01.45	08.45	EL	11 kv Disc Failed at Rice mill Nancharipetm village	
17		Mothkur	Mothkur Rural	11kv	Bhongir	17.40	20.40	03.00	EL	Mangal Gadda Near 11kv Pole Damedged	
18		Addagudur	Addagudur Agl	11kv	Bhongir	17.00	21.00	04.00	EL	2no.s 11kv Insulator & 11kv Disc & failed near Addagudur Village	
19		Addagudur	Kotamarthy	11kv	Bhongir	18.00	13.30	19.30	EL	2no.s 11kv Insulator & 11kv Disc failed near Kotamarthi Village	
20		Pallerla	Kurella	11kv	Bhongir	16.35	18.50	01.15	EL	Single Phase ok 3Phase B/d 11kv 1no Pole Damedged LT 3nos Pols Damedged	
21		Ambala	Ambala	11kv	Bhongir	01.45	08.30	06.45	EL	11 KV line snapped Near Ambala Village	
22		Ambala	Parupally	11kv	Bhongir	09.00	10.50	01.50	EL	11kv Line Snapped near Parupaly Village	
23		Choutuppal IPDS	Dhamera Agl	11kv	Choutuppal	16.01	09.33	17.32	EL	3 no's 11 kv Pole dammaged near Dhamera Village	
24		D.Nagaram	D.Nagaram Agl	11kv	Choutuppal	10.20	14.50	04.30	EL	11kv Disc Failed near D.Nagaram Village	
25		Jai kesaram	Jai kesaram Agl	11kv	Choutuppal	19.00	13.15	18.15	EL	11kv Insulator failed near Gokaram Cherru	
26		Jai kesaram	Jai kesaram indl	11kv	Choutuppal	08.00	10.00	02.00	EL	11kv Insulator Failed near Jai.Kesaram Villge	
27		Narayanpur	Maillacheru	11kv	Choutuppal	09.20	12.05	02.45	EL	SS-71 DTR Failed	
28		Golanpally	Nemalikaluva	11kv	Choutuppal	22.10	11.50	13.40	EL	2no's LT Poles Damedged & HT/LT Near Nemalikaluva Village	
29		Varkatpally	Gokaram	11kv	Choutuppal	14.10	15.40	01.30	EL	11kv Line Snapped & 11kv Disc Failed & 25kva DTR Failed near Gokaram Village	
1	RR N	Devarayamjal	Pothaipally	11kv	Medchal	07.20	09.20	02.00	BD	11KV Jumper cut and replaced at Madhu Thota	-
1	RR E	Pocharam	Jodimetla	11kv	Keesara	13.05	14.25	01.20		Tree fallen on 11kv line at Choudariguda	-
1	HYD N	Road No.13	Road No.1	11kv	X	05.02	06.12	01.10	EL,OL	End Kit failed at Sarve Hotel	
2		Marredpally	Military Hospital	11kv	C-VI	10.10	11.40	01.30	EL	Tree branches fallen on lines at 125 Betallion	