

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		2		2		2			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	0	5	0	5	0	5	0	0	



## TSSPDCL - LMRC / Corporate office

Date: 22.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Dirincherla	Yallapuram	11KV	Huzurnagar	11.30	13.00	01.30	EL	11 KV LINE SNAPPED	-
2		Bibinagar	Saketh india	11KV	Bhongiri	09.21	10.52	01.31	EL/OL	11 KV Pin Insulator failed near Mugdhumpally road Bibimagar	-
1	MDK	Anrich Bollaram	Sulaxshana-II	11KV	Patancheru	10.33	11.33	01.00		B/D due to Jumper cut	-
1	RR N	Bowrampet	Junnrum	11KV	Jeedimetla	14.10	15.17	01.07	EL	11kv AB Cable failure a Crikal School, Bowrampet X Road	-
2		Medicity	Pudur	11KV	Medchal	18.25	19.25	01.00	EL	11KV Conductor Snapped and replaced at near by SS	-