

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1							
2	NLG	144	988		4							
3	MDK	107	933		2							
4	SDPT				1							
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	0	0	0	0	0	
	Grand Total	1082	6468	0	10	0	2	0	2	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gangapur	Gollapally	11KV	Jadcherla	08.10	10.20	02.10		11KV Wire cut near Kolu Bai thanda	-
1	NLG	Nandipad	Iylapuram	11KV	Miryalguda	08.55	10.38	01.43	E/L	11Kv jumper cut near Iylapuram (V)	-
2		Yerkaram	Yerkaram	11KV	Suryapet	04.30	07.40	03.10	E/L	11Kv Insulator flashover	-
3		Chilukur	R C Nagar	11KV	Huzurnagar	05.50	07.30	01.40	E/L	11Kv Jumper Cut	-
4		Dondapahadu	Kakatiya	11KV	Huzurnagar	07.00	09.30	02.30	E/L	11Kv Jumper Cut	-
1	MDK	Gaddapotharam - I	Khajipally Indl.	11KV	Patancheru	15.05	16.15	01.10		BD Due to conductor snapped	-
2		Dundigal	Annaram	11KV	Patancheru	05.30	15.50	10.20		BD Due to Tree Fallen online	-
1	SDPT	Shanigaram	Begumpet	11KV	SDPT	04.30	07.30	03.00		B/D due to Insulator Felure	-
1	RR N	Jagathgirigutta	Jagathgirigutta	11KV	Medchal	14.50	16.05	01.15	BD	11KV Jumper touched to the Iron pole at near by SS	-
1	RR E	Moula-Ali	Mirzalaguda	11KV	Sainikpuri	18.50	20.45	01.55		UG Cable fail at Uppariguda Railway Track (L Insp Venkateshwar Rao)	-