

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988									
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	0	1	0	1	0	0	0	
	Grand Total	1082	6468	1	2	1	2	1	2	0	0	

TSSPDCL - LMRC / Corporate office

Date: 31.03.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivpet	Koheer	33KV	Sangareddy	6:40	7:15	0:35		Tripped due to phase to phase touched, intermediate pole erected and charged	Koheer	At 07.15 hrs. Alternate supply arranged from 132KV Zaheerabad - 33KV Jarasangam Regular feeder charged at 10.20 hrs.

TSSPDCL - LMRC / Corporate office

Date: 31.03.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Nacharam Indore	Mallikarjuna Nagar	11KV	Habsiguda	7:16	8:11	0:55		11KV Jumper cut at Nacharam & Chilaka Nagar Boarder	No
1	HYD N	R.P.Nilayam	R.P.Nilayam -II	11KV	C-VI	10.12	11.14	01.02	EL	Faulty loads of 11KV Rythu Bazar feeder	No