

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988									
3	MDK	107	933									
4	SDPT			2	1	2	1	2	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>2</b>	<b>4</b>	<b>2</b>	<b>4</b>	<b>2</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 03.05.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shanthinagar - I	33KV	Gadwal	17.53	20.02	02.09		Tree branches fallen on the line Kallukuntla	Shanthinagar - I	No
2		Alampur	Shanthinagar - II	33KV	Gadwal	17.52	19.50	01.58		Tree branches fallen on the line near Maddur stage	Shanthinagar - I	No
1	SDPT	Duddeda	Kondapak	33KV	Gajwel	13:15	15:15	2:00		Tree fallen on 33KV line near Marpadaga SS	Kondapak	No
2		Gajwel	Shivams feeder	33KV	Gajwel	12.55	17.55	05.00		LA Problem at Rani break line company	Shivams Feeder	No

TSSPDCL - LMRC / Corporate office

Date: 03.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDPT	Komuravelly	Komuravelly	11KV	Husnabad	7:05	11:26	4:21		Disc failed	No
1	HYD N	Gunrock	Medchal	11KV	C-VI	19.00	20.51	01.51	EL	Twisted lines at Arch Stone Building	No