

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		8		8		8			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	9	0	9	0	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	13	1	13	1	13			
3	MDK	107	933									
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	18	3	18	3	18	0	0	
	Grand Total	1082	6468	3	27	3	27	3	27	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Surya Jyothi	33KV	Jadcherla	13.10	14.20	01.10	E/L&O/L	No Visbule Fault		-
2		Shadnagar	Shadnagar	33KV	Mogiligidda	10.30	12.10	01.40	E/L	Pin Binding Replaced at Elikatta Village		-
1	NLG	MADGUALAPLLY	THADAKAMALLA	33KV	Miryalguda	19.30	08.10	12.40	EL/OL	33KV INSULATOR FAILED AT SEETHYA THANDA SS		-

Circle-wise 11KV Breakdowns

Date: 05.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Urumadla	T.Vellemla	11KV	Nalgonda	12.00	13.10	01.10	E/L	11KV Line Insulator Failur SS-2	-
2		Arjalabavi	Arjalabavi AGL	11KV	Nalgonda	06.00	11.00	05.00	E/L	Tree Branches On The Line	-
3		Anneparthi	Anneparthi AGL	11KV	Nalgonda	11.00	14.00	03.00	E/L	11KV Line Cutting	-
4		Thimmannagudem	Narsimhapuram	11KV	Nalgonda	03.30	07.30	04.00	E/L	HT/HT Melting	-
5		THADAKAMALLA	SETTIPALEM	11KV	Miryalguda	19.40	15.10	19.30	E/L	11Kv POLE DAMAGED & S-PH CABLE CUT	-
6		THADAKAMALLA	THADAKAMALLA	11KV	Miryalguda	19.40	10.40	14.40	E/L	11Kv POLE DAMAGED	-
7		Phanigiri	Anantharam	11KV	Suryapet	10.40	13.10	02.30	E/L	11Kv Insulator failed	-
8		Raghunadapalem	Gundlapally	11KV	Huzurnagar	13.00	14.45	01.45	E/L	11 KV LINE SNAPPED	-
9		Chamapur	Chandepally	11KV	Bhongir	01.40	14.00	12.40	EL/OL	SS-7 11KV Insulator Filled	-
10		Manaikunta	Veldevi	11KV	Bhongir	18.50	12.30	17.40	EL/OL	Buffalo Ded 11kv Luse Line Fault	-
11		Kapraipally	Kapraipally	11KV	Bhongir	21.30	09.00	11.30	EL/OL	11kv Insualtor Failed near Kapraipally (V)	-
12		Jangam	Wachathanda	11KV	Choutuppal	14.00	16.20	02.20	EL/OL	11kv Insultor Failed near Sub_station	-
13		Voligonda	Mandapuram	11KV	Choutuppal	16.00	18.30	02.30	EL/OL	12no's 11kv pole dammages & 6no's LT Pole dammages	-
1	SDPT	PAMULAPARTHY	PAMULAPARTHY LC No.3254	11KV	Gajwel	09.30	11.00	01.30		LT Poles Damaged	-
2		MULUGU	BAILAMPUR AGL LC. No 13189	11KV	Gajwel	12.10	14.10	02.00		Jumper Cut	-
3		DOMMATA	SURAMPALLI LC. No 12079	11KV	Gajwel	18.25	21.15	02.50		Jumper Cut	-
4		Husnabad	Pandilla	11KV	Husnabad	11.05	12.10	01.05		Line Cut	-
5		Dhulmitta	Dhulmitta Agl	11KV	Husnabad	02.30	08.50	06.20		Line Cut	-
1	RR E	Cherlapally-V	Pedda Cherlapally	11KV	Sainikpuri	16.04	17.29	01.25		11Kv line Brass patti cut near Pedda Cherlapally Park and Due to Heavy wind (AE)	-
2		Chengicherla	My Villas	11KV	Keesara	16.25	17.25	01.00		11KV Brass patti cut near Peddamma Temple	-
3		Chakripuram	Shilpa Nagar	11KV	Keesara	16.00	17.30	01.30		11KV line twisted at Vidya Balan School	-
4		Nagaram	Bandlaguda	11KV	Keesara	16.25	17.56	01.31		Tree branches fallen on 11kv line near Modi Builders	-
5		Yadgarpally	Cheeryala	11KV	Keesara	16.25	17.30	01.05		Tree branches fallen on 11kv line near SS Yard Backside	-
6		Yadgarpally	Thimmaipally	11KV	Keesara	16.25	17.30	01.05		Tree branches fallen on 11kv line near SS Thimmaipally Grama Panchayathi	-
7		Aushapur	Sandupatlaguda	11KV	Keesara	16.40	17.10	00.30		11KV Pin Insulator failed at Sandupatlaguda Petrol Bunk	-
8		Aushapur	Madharam	11KV	Keesara	17.10	18.10	01.00		Tree branches fallen on 11kv line near Narayana Reddy Poultry Form	-
1	HYD S	Gosha Mahal	Feelkhana	11KV	IX	19.34	20.45	01.11	EL	Cable fault	Arranged B/F on 11KV Osmangunj fdr