

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		14		14		14			
	Total	606	3055	0	17	0	17	0	17	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	1	4	1	4	1			
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933									
4	SDPT			2	27	2	27	2	27			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	7	31	7	31	7	31	0	0	
	Grand Total	1082	6468	7	48	7	48	7	48	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Surya Jyothi(MYK)	33KV	Jadcherla	15.05	15.55	00.50	E/L	Line Isolator Opened Supply Stood OK near RG Rotopack Industry		
2		Puttapad	Salkarpet	33KV	Narayanapet	18.08	19.25	01.17	E/L	Tree follen on the line & coundertor snapped salkarpet		No
3		leeza	Madelabanda	33KV	Gadwal	22.45	02.25.00 (07.05.20)	03.50	E/L	Insulator flash over		No
4		Gadwal	Nandine	33KV	Gadwal	21.31	00.20.00 (07.05.20)	02.49	E/L	Tree follen on the line		AB Switch open
1	NLG	Miryalaguda	Tripuraram	33KV	Miryalaguda	17.25	18.52	01.27	EL/OL	Conductor snapped		-
1	SDPT	HUSNABAD	THOTAPALLY	33KV	Husnabad	15.15	16.50	01.35		Under Breakdown		Altenate supply taken from 33kv katkur feeder on 16:50 Hrs
2		Palamakula	Rajagopalpet	33KV	Siddipet	15.30	16.50	01.20		Insulater Broken		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 06.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Boothpur	Amistapur	11KV	Jadcherla	09.00	11.00	02.00		11 KV wire cut at siddaiapally.	-
1	NLG	Jalalpuram	Velishala	11KV	Suryapeta	09.30	12.30	03.00	EL	Insulator failed	-
2		Nadigudem	Karvirala	11KV	Huzurnagar	09.30	12.30	03.00	EL	Due to 11kv line Cutted	-
3		Peddathanda	Peddathanda	11KV	Bhongiri	15.15	16.40	01.25	EL	Insulator failure	-
1	SDPT	33/11KV SS POTHARAM	MIRZAPOOR	11KV	Husnabad	16.30	17.30	01.00		Conductor snapped	-
2		33/11KV SS DHARMARAM	Dharmaram(R.)	11KV	Husnabad	15.10	17.30	02.20		Insulator failed	-
3		33/11KV SS DHARMARAM	Nandaram	11KV	Husnabad	15.10	17.30	02.20		Conductor snapped	-
4		33/11KV SS DHARMARAM	Potharam(J)	11KV	Husnabad	15.10	17.30	02.20		Conductor snapped	-
5		Pandilla	Kuchanapally	11KV	Husnabad	15.30	18.10	02.40		11kV jumper cut	-
6		33/11KV SS Cherial Town	Cherial-Town	11KV	Husnabad	15.05	16.30	01.25		Conductor snapped	-
7		33/11KV SS Cherial Town	Balaji takis	11KV	Husnabad	15.05	16.10	01.05		11kV jumper cut	-
8		33/11KV SS Gurjakunta	Vechareni	11KV	Husnabad	15.50	16.20	00.30		11kV jumper cut	-
9		33/11KV Komaravelly	Kistampet	11KV	Husnabad	14.55	16.50	01.55		Tree fallen	-
10		33/11KV SS Chityal	Chityal Agl	11KV	Husnabad	15.10	17.10	02.00		Insulator failed	-
11		MARKOOK	BHAVANANDAPUR AGL LC. No 25223	11KV	Gajwel	08.01	10.33	02.32		Transformer Failure	-
12		DAMARAKUNTA	INDUSTRIAL LC.No 30259	11KV	Gajwel	13.30	16.01	02.31		Jumper Cut	-
13		DAMARAKUNTA	KAKIREDDYPALLY LC.No 30260	11KV	Gajwel	13.30	17.04	03.34		Jumper cut	-
14		DAMARAKUNTA	KAKIREDDYPALLY LC.No 30261	11KV	Gajwel	18.16	19.18	01.02		Jumper Cut	-
15		WARDARAJPUR	SHIVAVENKATAPU R LC. No 25047	11KV	Gajwel	13.36	16.40	03.04		Tree Branch fallen on 11kV Line	-
16		WARDARAJPUR	WARDARAJPUR LC.No 25048	11KV	Gajwel	13.25	19.35	06.10		Jumper Cut	-
17		ERRRAVALLY	ERRAVALLY AGL LC.No 5191	11KV	Gajwel	13.45	19.40	05.55		Jumper Cut	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
18		ERRRAVALLY	NARSANNAPETA LC. 5192	11KV	Gajwel	17.14	18.42	01.28		Transformer Failure	-
19		DUDEEDA	INDUSTRIAL LC.No 21231	11KV	Gajwel	16.40	18.25	01.45		Pin Insulator Fail	-
20		DUDEEDA	CHALAMPUR LC.No 21232	11KV	Gajwel	16.40	18.40	02.00		Tree branch fall over 11KV	-
21		MEDINIPUR	KUKUNOORPALLY TOWN LC.No 137	11KV	Gajwel	11.20	16.55	05.35		Insulator Fail	-
22		MATHPALLY	MATHPALLY LC.No 14365	11KV	Gajwel	09.25	11.20	01.55		3-ph Breakdown due tree branch fall over 11kV line	-
23		MOBARASPUR	THIRUMALAPUR AGL LC.No 11640	11KV	Gajwel	15.42	19.06	03.24		11KV Line Cut due to tree branch fall over line	-
24		MOBARASPUR	MOBARASPUR LC.No 11641	11KV	Gajwel	15.08	19.06	03.58		Jumper cut near yard	-
25		MOBARASPUR	MALLESHAMPALLY LC.No 11642	11KV	Gajwel	16.42	19.39	02.57		HT/LT Cable burst	-
26		Komaticheruvu	Srinagar Colony	11KV	Siddipet	17.10	18.00	00.50		B/D 11KV wire cut, LC No 36287	-
27		Ramancha	Gangapur	11KV	Siddipet	18.10	19.20	01.10		B/D tree branches fallen on the line	-
1	RR N	GP Pally	APIIC	11KV	Medchal	17.55	19.05	01.10	BD	Tree fallen on the 11KV Line at Chermas	-
1		NGRI	Anandbagh	11KV	Habsiguda	16.26	17.46	01.20		11KV AB Switch Insulator failed at Jaheed Nagar	-
2	RR E	Kalyanipuri	NMDC	11KV	Sainikpuri	17.16	21.26	04.10		Post off Insulator Blast at Tharun Evenue Aport. & Pin Insulator failed at East Anandbagh & Pin Insulator replacement at Vijaya Vinayaka Aport. & Pin Insulator Blast at Sai Krupa Aport. & Tree braanches fallen on 11Kv line at Increcet Enclave (L.Insp Ramulu)	-
1	HYD N	R.P.Nilayam	Raithu Bazar	11KV	Bowenpally	17.50	19.18	01.28	OL-R&Yph	No Visible Fault	Arranged B/F on 11KV Chinthal Bazar fdr
1		Panjesha	Panjesha	11KV	Charminar	10.45	11.49	01.04	All Indication	Cable damaged by GHMC Wing	Partial fdr charged & remaining loads added on 11KV Charminar fdr
2		Devibagh	Rama Talkies	11KV	Charminar	16.58	18.14	01.16	EL,OL	UG Cable fault at Rama Talkies	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
3	HYD S	Devibagh	Zoo Quarters	11KV	Charminar	16.58	19.38	02.40	EL,OL	Tree branches fallen on lines at V.P School	-----	
4		Aliabad	Masrath Function Hall	11KV	Charminar	17.17	18.57	01.40	OL-Rph	Big tree fallen on lines at Shama Talkies	-----	
5		Attapur	HUDA Colony	11KV	Charminar	17.46	19.10	01.24	EL	Tree branches fallen on lines at HUDA Colony	-----	
6		Khilwath	Khilwath	11KV	Charminar	23.56	01.20	01.24	OL-Rph	Cable End Kit fault at Gulshan Gafoor Apartment	Arranged B/F on 11KV Kamela fdr	
7		Malakpet	M.M.H	11KV	Asmangadh	17.10	19.30	02.20	All Indication	Tree branches fallen on lines & Brass Patti cut at Metarnity Hospital	-----	
8		Seetharam Bagh	Seetharam Bagh	11KV	Begumbazar	17.05	18.13	01.08	EL,OL	Insulator flash over at Kubha Mandir	-	
1		HYD C	Chilkaiguda	Parsigutta	11KV	Azamabad	17.15	18.45	01.30	EL,OL	No Visible Fault	-
2			Batkammakunta	D.D.Colony	11KV	Azamabad	16.25	18.05	01.40	EL,OL	AB Switch sparking at B-Line	-
3	Fever Hospital		C.C.S Hospital	11KV	Azamabad	16.58	18.20	01.22	EL,OL	Jumper cut at Raghavendra Apts	-	
4	Batkammakunta		Ahobilmutt	11KV	Azamabad	17.02	18.15	01.13	EL	Tree branches fallen on lines at Krishna Teja Apts	-	
5	Chilkaiguda		Golconda X Road	11KV	Azamabad	17.10	18.30	01.20	EL,OL	HT Jumper cut at MBK Estate	-	