

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	8	0	8	0	8	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		4		4				
2	NLG	144	988		2		2		2			
3	MDK	107	933		2		2		2			
4	SDPT			1	15	1	15	1	15			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	19	5	19	5	19	0	0	
	Grand Total	1082	6468	5	27	5	27	5	27	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Devarkadra	33KV	Narayanapet	20.25	22.30	02.05	E/L	Due to Line Twisted	Narayanapet	Alternate Supply Arranged from 33KV Koukuntla at 21:25Hrs.
2		Kosgi	Surayapally	33KV	Narayanapet	21.30	23.12	01.42	E/L	Pin Type Insulator Disc Damaged Near Chellapur	Narayanapet	NO
3		Ghanapur	Lattupally	33KV	Wanaparthi	21.53 (09.05.20)	06.00 (10.05.20)	08.07	E/L	Due to Rain	Wanaparthi	NO
4		Alwal	Padkal	33KV	Shadnagar	20.51	23.45	02.54	E/L	Insulator Damaged at Padigadda Line	Shadnagar	NO
1	SDP	Gajwel	KDA	33KV	Gajwel	16.40	18.05	01.25			BD Insulater replaced	KDA

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 09.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thatipamula	Sri Ram Thanda	11KV	Suryapet	14.00	17.00	03.00	E/L	11Kv Jumper cut	-
2		Ananthagiri	Kistapuram	11KV	Huzurnagar	08.00	09.20	01.20	E/L	11Kv Line Snapped	-
1	MDK	Fasalwadi	MNR	11KV	Sangareddy	17.30	19.30	02.00		BD due to Jumper cut	-
2		Ismailkhanpet	Erdanoor	11KV	Sangareddy	17.30	19.30	02.00		BD due to Jumper cut	-
1	SDP	JAGADEVPUR	JAGADEVPUR AGL	11KV	Gajwel	08.37	10.47	02.10		Disc Fail and Conductor Brust	-
2		MULUGU	NARSAMPALLY AGL	11KV	Gajwel	17.15	18.20	01.05		Jumper Cut	-
3		TUNIKI BOLLARAM	ACHAYAMPALLI	11KV	Gajwel	10.50	14.00	03.10		Disc fail	-
4		DUDEEDA	INDUSTRIAL	11KV	Gajwel	17.40	18.10	00.30		11KV Poles Damaged	-
5		MUBARASPUR	THIRUMALAPUR AGL	11KV	Gajwel	17.25	18.45	01.20		Insulator Fail	-
6		ANAJIPUR	MANTHUR	11KV	Gajwel	11.40	12.26	00.46		Disc Failure	-
7		ANAJIPUR	ANAJIPUR	11KV	Gajwel	19.00	20.03	01.03		LT line Conductor Brust	-
8		RAIPOLE	RAIPOLE AGL	11KV	Gajwel	14.23	15.33	01.10		Jumper Cut	-
9		RAIPOLE	INDUSTRIAL	11KV	Gajwel	17.40	18.17	00.37		Jumper Cut	-
10		LINGAPUR	CHANDAPUR	11KV	Gajwel	17.00	18.30	01.30		Tree Branch fall over 11KV line	-
11		HUSNABAD	HUSNABAD TOWN-2	11KV	Husnabad	10.48	02.24	06.00		Due to Wind Effect	-
12		THOTAPALLY	MALLAMPALLY	11KV	Husnabad	00.00	00.00	00.00		3-PH BD Tree fallen on line	-
13		RAMCHANDRAPUR	VINJAPALLY	11KV	Husnabad	00.00	12.00	12.00		Tree fallen on line	-
14		BASWAPUR	MUTHANNAPET	11KV	Husnabad	10.48	01.12	04.48		Due to Wind Effect	-
15		REBARTHY	MADDUR	11KV	Husnabad	00.00	07.12	07.12		Tree fallen on line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal Bhagath	Satya nagar	11KV	Habsiguda	18.07	18.48	00.41		Tree fallen on 11kv line at Satya nagar	-
2		Uppal	Chilka nagar	11KV	Habsiguda	06.20	07.40	01.20		11KV Line snapped at Ganesh nagar Chru & Braker mechanical falt & Backfeeding to Adharsh nagar feeder	-
3		Uppal	Navbharath	11KV	Habsiguda	17.50	19.00	01.10		Tree fallen on 11kv line at Video cone showroom	-
4		Singapur	Annojiguda	11KV	Keesara	18.35	20.05	01.30		Tree fallen on 11kv line at Laxmi narshima road	-
5		GKSR	Shiva reddyguda	11KV	Keesara	18.30	20.20	01.50		Insulaotr fail at Maisammagutta	-
6		GKSR	Kondapur AGL	11KV	Keesara	18.30	21.20	02.50		Tree fallen on 11kv line at Kondapur village	-
1	HYD N	Road No.2	Shabdalya	11KV	X	02.55	04.22	01.27	EL,OL	Cat fallen in 5Way R.M.U at Sagar Society Signals	Loads transferred onto 11KV Amrutha fdr
1	HYD C	Golnaka	Moulana Azad Nagar	11KV	II	16.32	17.46	01.14	EL	Cable End Kit fault at Kowli Garden, Chappal Bazar	-