

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	5	2	5	2	5			
2	NLG	144	988		2		2		2			
3	MDK	107	933	1	7	1	7	1	7			
4	SDPT			3	22	3	22	3	22			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	36	6	36	6	36	0	0	
	Grand Total	1082	6468	6	38	6	38	6	38	0	0	

TSSPDCL - LMRC / Corporate office

Date: 10.05.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effectuated	Alternate Supply Arranged
1	MBNR	Maddur	Kothapally	33KV	Narayanapet	01.10	06.35	05.25	EL	Top Insulator Failed	Kothapally	No
2		Maddur	Pallerla	33KV	Narayanapet	01.10	08.25	07.15	EL	Insulator failed & Tree fallen on the line	Pallerla	No
1	MDK	Gummadidala	GPSS-2	33KV	Patancheru	10:30	11:35	1:05		Line isolator jumper snapped	GPSS-2	No
1	SDPT	Doulthabad	Raipole	33KV	Gajwel	10:13	12:16	2:03		Pin insulator failed	Raipole	No
2		Doulthabad	Gurralasoffa	33KV	Gajwel	10:13	12:16	2:03		Pin insulator failed	Gurralasoffa	No
3		Habsipur	Thimmapur	33KV	Siddipet	9:30	10:00	0:30		Lighting arrester failed near 33 kv Thimmapur SS	Thimmapur	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Gangapur	11KV	Jadcherla	10.15	14.40	04.25		11KV Wire cut near Yerragutta	No
2		Midjil	Boinpally	11KV	Jadcherla	00.00	01.30	01.30		11KV Wire cut near SS	No
3		Midjil	Veljal	11KV	Jadcherla	06.30	14.00	07.30		Phase to Phase near Veljal	No
4		Rajapur	Chennavelly	11KV	Jadcherla	9:00	12:00	3:00		11KV Wire cut Kucharkal	No
5		Marrikal	Malkapur	11KV	Jadcherla	07.15	08.45	01.30		11KV Insulator fail near Malkapur	No
1	NLG	Palakaveedu	Nagireddigudam	11KV	Huzurnagar	5:50	8:30	2:40	EL	11KV Jumper cut	No
2		Nemaragommula	Jiyapally	11KV	Bhongiri	00.10	08.58	08.48	EL/OL	11KV Pin insulator failed near Mahadevapur village	No
1	MDK	Fasalwadi	MNR	11KV	Sangareddy	11:05	12:45	1:40		Insulator failed	No
2		Pati	My Home	11KV	Patancheru	10.20	12.50	02.30		CT PT Failure	No
3		Pati	Ionnex	11KV	Patancheru	06.15	07.35	01.20		CT PT Failure	No
4		Patancheru Town	Shanthinagar	11KV	Patancheru	09.20	10.40	01.20		Due to heavy Rain	No
5		Kistareddypet	Patelguda	11KV	Patancheru	11.35	13.20	01.45		11KV Jumper cut	No
6		Bollaram - II	Rupa	11KV	Patancheru	08.33	09.42	01.09		Tree fallen on the line	No
7		Gundla Machnoor	Arch Pharma	11KV	Patancheru	12:30	17:20	4:50		Cable Kit failed	No
1	SDPT	RAMCHANDRAPUR	VINJAPALLY	11KV	Husnabad	11:20	11:50	0:30		Due to gale & wind	No
2		REGULAPALLY	CHEELAPUR	11KV		6:00	9:35	3:35		Due to gale & wind	No
3		Cherial Town	Sundarayyanagar Ag	11KV		9:05	13:15	4:10		Due to gale & Wind (Line Snapped)	No
4		Akunoor	Dommata	11KV		9:10	11:25	2:15		Due to gale & Wind	No
5		Gurjakunta	Gurjakunta 24 hrs	11KV		11:50	16:05	4:15		Due to gale & Wind	No
6		Gurjakunta	Gurjakunta Agl	11KV		9:00	11:45	2:45		Due to gale & Wind	No
7		Gurjakunta	Vechareni	11KV		17:25	19:10	1:45		Due to gale & Wind	No
8		Komuravelly	Posanpally	11KV		6:30	7:20	0:50		Due to gale & Wind	No
9		Chityal	Chityal Agl	11KV		0:00	12:40	12:40		Poles damaged	No
10		Chityal	Dommata	11KV		0:00	17:00	17:00		Poles damaged	No
11		Chityal	Thadoor	11KV		0:00	18:05	18:05		Poles damaged	No
12		Marmamula	Marmamula	11KV	0:00	10:34	10:34		Due gale & wind	No	
13		KODAKANDLA	KUKNOOR PALLY	11KV	11:55	13:30	1:25		TREE CUTTING	No	
14		GANESH PALLY	ANGADI KISTAPUR	11KV	09:45	10:05	0:20		11KV LINE BURN	No	
15		GOWRARAM	GOWRARAM TOWN	11KV	12:10	12:33	0:23		BREAK DOWN	No	
16		MEDNIPUR	KUKNOOR PALLY	11KV	12:00	13:20	01:20		AB SWITCH REPAIR	No	
17		DUDEEDA	DUDEEDA AGL	11KV	07:42	09:40	01:58		TREE FALLEN ON THE 11 KV LINE	No	
18		THUKKAPUR	THOGUTA AGL	11KV	7:10	15:00	7:50		INSULATOR FAILED	No	
19			KANGAL	11KV	11:45	13:55	2:10		TREE CUTTING	No	
20			P. S & THUKKAPUR	11KV	9:05	13:30	4:25		33KV MIDDLE POLE WORK	No	
21		GUDIKANDLA	ANDHAY	11KV	12:20	15:20	3:00		11KV LINE CUT	No	
22		METTU	BANDAR PALLY	11KV	11:40	15:30	4:10		MIDDLE POLE WORK	No	
1	RR N	Kandlakoya	Saigeetha Ashramam	11KV	Medchal	11:00	12:15	1:15		11KV Pin insulator failed and replaced at Police Training Center	No
1	RR E	CRPF	Chennapur	11KV	Keesara	23:20	0:20	1:00		Lorry Dash to DTR in Dumping yard	No