

Status Report on Breakdowns (Urban / Rural)

Urban

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------|------------------------------|------|------------------------------------|------|-------------------------|------|-------------------------------------|------|--------------------------------|------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | 1 | | 1 | | 1 | | | |
| 6 | RR(N) | 54 | 550 | | | | | | | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | 1 | 6 | 1 | 6 | 1 | 6 | | | |
| | Total | 606 | 3055 | 1 | 7 | 1 | 7 | 1 | 7 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|-------------|-------------------------------|------|------------------------------------|------|-------------------------|------|-------------------------------------|------|--------------------------------|------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | 2 | 1 | 2 | 1 | 2 | 1 | | | |
| 2 | NLG | 144 | 988 | | 1 | | 1 | | 1 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 2 | 2 | 2 | 2 | 2 | 2 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 3 | 9 | 3 | 9 | 3 | 9 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 12.05.2020

Circle-wise 33KV Breakdowns

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|-----------------------|---------------------------|
| 1 | MBNR | Kodangal | Peddandandigama | 33KV | Vikarabad | 12.05 | 14.15 | 02.10 | EL | Lizard follen on the 33KV line | Kodangal | - |
| 2 | | Alampur | Shanthinagar -1 | 33KV | Gadwal | 15.35 | 18.15 | 02.40 | EL | Tree follen on the 33KV line near Sriramnagar | Alampur | - |
| 1 | HYD N | 132KV Madhapur | Vanen Burg | 33KV | Kalyan Ngr | 12.46 | 13.23 | 00.37 | EL,OL-R&Yph | Cable damaged by GHMC wing at Lemon Tree Hotel | 132KV Madhapur | - |

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 12.05.2020

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|--------------------|---|-----------------------------------|
| 1 | MBNR | Balanagar | Gouthapur | 11KV | Jadcherla | 07.20 | 12.24 | 05.04 | | DTR Fail Near at Ammapally (v) | - |
| 1 | NLG | Keethavarigudem | Laxmipuram | 11KV | Huzurnagar | 07.20 | 10.20 | 03.00 | EL | Due to 11kv insulator failure | - |
| 1 | RR S | Nanakramguda | Church | 11KV | Gachibowli | 13.36 | 14.42 | 01.06 | | Flexi Fallen on the 11kv line near outer Ring Road at Nanakramguda. | - |
| 1 | HYD N | Nehru Nagar | Contonement | 11KV | Bowenpally | 16.07 | 17.49 | 01.42 | A/R Opened | Tree branches fallen on lines at Axis Bank | - |
| 2 | | James Street | Chikoti Complex | 11KV | Sec-Bad | 16.10 | 17.42 | 01.32 | EL,OL | Pin Insulator flash over at Chikoti Nala | - |
| 3 | | Patigadda | KIMS Road | 11KV | Sec-Bad | 16.20 | 18.10 | 01.50 | EL | Jumper touching to channel at Opp:KIMS SS | - |
| 4 | | Begumpet | Play Ground | 11KV | Erragadda | 16.40 | 18.05 | 01.25 | EL | No Visible Fault | - |
| 5 | | E.S.I | IAS Quarters | 11KV | Erragadda | 18.16 | 19.18 | 01.02 | EL,OL & A/R Opened | AB Cable sparking at Srinivasa Colony East | - |
| 1 | HYD C | Golnaka | Harazpenta | 11KV | Azamabad | 11.18 | 12.43 | 01.25 | EL,OL | Cable fault at Harazpenta | Arranged B/F on 11KV Prabhath fdr |