

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Undavelly	33KV	Gadwal	19.08	19.55	00.47	EL/OL	Under Breakdown		Alternate Supply Arranged from 33KV Alampurfeeder at 19.55 hrs

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 13.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Alair	Ikkurthy	11KV	Bhongir	00.05	06.50	06.45	EL/OL	11kv Insulator failed near Bypass road Alair town.	-
2		Malkapur	Thuprampet Agl	11KV	Choutuppall	00.06	07.55	07.49	EL/OL	11kv line snapped at Mailaram road near Thuprampet (V)	-
1	SDPT	JAGADEV PUR	ATRAJPET (LC NO:6998)	11KV	Gajwel	18.36	20.10	01.34		DISK FAILED	-
2		MARKOOK	MARKOOK AGL (LC NO:25236)	11KV	Gajwel	10:40	12:50	00.10		11 KV WIRE CUT	-
3		YETIGADDA KISTAPUR	THIRUMALA GIRI (LC NO:20147)	11KV	Gajwel	09.06	10.38	01.32		POLE DAMAGE	-
4		RAMPUR	RAMPUR (LC NO:10126)	11KV	Gajwel	08.00	11.00	03.00		INSULATOR FAILED	-
5		Gurrallagundi	Malyala	11KV	Siddipet	00.44	11.00	10.16		B/D	-
1	RR S	Nanakramguda	N'Widia	11KV	Gachibowli	14.20	15.28	01.08		Water tanker dashed to 11kv Pole at Continetal hospital	-
1	RR E	IDAUppal	Airtel	11KV	Habsiguda	06.00	09.06	03.06		11Kv cable failed near Dumping yard & B/F to srikrishna feeder	-
1	HYD C	Golnaka	Nehru Nagar	11KV	Azamabad	00.33	01.37	01.04	EL	No Visible Fault	-
2		Industrial Area	V.S.T.	11KV	Azamabad	08.40	13.30	04.50	All Indication	CT PT failed at SS & End Kit failed at VST Company (Consumer side problem)	-