

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	4	11	4	11	4	11			
3	MDK	107	933									
4	SDPT			1	14	1	14	1	14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	26	5	26	5	26	0	0	
	Grand Total	1082	6468	5	32	5	32	5	32	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.05.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramannapeta	Chityala	33KV	Nalgonda	14:28	18:00	3:32	EL	3 Nos. 33 KV Insulators Damaged and 33 KV Jumper Cut	Chityala	No
2		Ramannapeta	Velminedu	33KV	Nalgonda	16.05	20.00	03.55	EL	Jumper Cut	Velminedu	No
3		Kodandapur	Mission Bhagiradha	33KV	Devarakonda	15.30	20.10	04.40	EL	Disk brake	Mission Bhagiradha	No
4		Mothkur	Pallerla	33KV	Bhongir	13.55	16.30	02.35	EL	2no's 33kv Poles Damaged near Pallerla Village Due to Heavy Gale & Wind	Pallerla	No
1	SDPT	Thukkapur	Mirdoddy	33KV	Gajwel	17:25	19:15	1:50		Conductor snapped	Mirdoddy	At 19.15 hrs. Alternative supply arranged from 132KV Habsipur - 33KV Khajipur

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Peddarevelly	11KV	Jadcherla	02.20	07.20	05.00		11 KV line cut near peddarevelly.	No
1	NLG	Madgulapally	Dacharam	11KV	Nalgonda	14:15	16:20	2:05	EL	Due to Heavy Rain and Wind	No
2		Arlagaddagudem	Ch.Suraram	11KV	Nalgonda	14.15	17.40	03.25	EL	Jumper Cut	No
3		Kethepally	Korlapahad	11KV	Nalgonda	14.25	16.00	01.35	EL	Due to Heavy Rain and Wind	No
4		Velgupally	Velgupally	11KV	Nalgonda	14.20	16.00	01.40	EL	Jumper Cut	No
5		Kattangur	Mallaram	11KV	Nalgonda	14.50	15.40	00.50	EL	Due to Heavy Rain and Wind	No
6		Kattangur	Bollepally	11KV	Nalgonda	14.50	15.40	00.50	EL	Due to Heavy Rain and Wind	No
7		AGAMOTHKUR	AGAMOTHKUR	11KV	Miryalaguda	00.00	10.50	10.50	EL	11 KV Conductor snapped at agriculture field	No
8		Annaram	Kothagudem	11KV	Suryapet	05.00	08.10	03.10	EL	Insulator failed	No
9		Akupamula	Singaram	11KV	Huzurnagar	07.35	09.30	01.55	EL	11 KV Line snapped	No
10		Raigiri	Raigiri Agl	11KV	Bhongir	07.00	09.50	02.50	EL	11 KV Insulator failed near Raigir village	No
11		Addagudur	Addagudur	11KV	Bhongir	20:30	13:00	16:30	EL	11 KV Line Snapped near Addagudur Village	No
1	SDPT	Ponnala	Ponnala Agl	11KV	Siddipet	14:00	16:30	2:30		Trees fallen on the 11KV line	No
2		Ponnala	All feeders	11KV	Siddipet	17:35	19:55	2:20		33KV line	No
3		Gambeerpur	Gambeerpur	11KV	Siddipet	15:40	16:10	0:30		LT line	No
4		Jagadevpur	Town Feeder	11KV	Gajwel	11:42	12:28	0:46		Tree branches fallen	No
5		chatlapally	Anthaiguda	11KV	Gajwel	20:00	23:55	3:55		Insulator failed	No
6		Munigadapa	Wattipally	11KV	Gajwel	12:49	13:43	0:54		HT By LT Touching	No
7		Munigadapa	Watipally	11KV	Gajwel	19:31	21:45	2:14		Jumper cut	No
8		Markook	Markook Agl	11KV	Gajwel	11:10	12:10	1:00		Pole Broken	No
9		Pamulaparthi	Ippalagudem Feeder	11KV	Gajwel	9:46	10:50	1:04		Cable fault	No
10		Nacharam	Nacharam Temple	11KV	Gajwel	11:40	15:30	3:50		Limb failed	No
11		Duddeda SS	Rampally Feeder	11KV	Gajwel	5:40	9:30	3:50		No visible fault	No
12		Doulthabad	SP Bandaram Feeder	11KV	Gajwel	9:08	10:33	1:25		LT Line Cut	No
13		Doulthabad	Deepayampally Feeder	11KV	Gajwel	9:36	11:30	1:45		Pad Clamp failed	No
14		Akunoor	Domata	11KV	Husnabad	6.55	10.00	3.45		Conductor Snapped	No
1	RR N	ICICI	Bharathbiotech	11KV	Medchal	16:25	18:00	1:35		Tree fallen on the 11KV line near Bharathbiotech Company	No
1	RR E	Saketh	Pranam	11KV	Sainikpuri	18:30	19:30	1:00		Tree branches fallen on 11KV line at Phase-I & LT pole damage	No
2		NN Colony	Jai Jawan	11KV	Sainikpuri	18.04	19.05	01.01		Tree branches fallen on 11KV line at Ashok Manoj Colony	No
3		NN Colony	Jammigadda	11KV	Sainikpuri	18.18	19.10	00.52		Tree branches fallen on 11KV line at Jai Kishan Colony	No
4		Vayupuri	Vayupuri	11KV	Sainikpuri	19.20	20.27	01.07		11KV Jumper cut at Vayupuri Water Tank	No
1	HYD C	Asif Nagar	Jyothi Nagar	11KV	VII	17.00	18.55	01.55	EL	Telephone wire touching to HT Line at Jyothi Colony	No