

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT				18		18		18			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	25	3	25	3	25	0	0	
	Grand Total	1082	6468	3	31	3	31	3	31	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Narayanapet	Narayanapet 1	33KV	Narayanapet	14.20	15.55	01.35	OL	Phase to Phase near Apapaply Village	Narayanapet	-
2		Narayanapet	Chinnajetram	33KV	Narayanapet	14.20	15.55	01.35	OL	Phase to Phase near Apapaply Village	Narayanapet	-
3		Maddur	Vepoor	33KV	Narayanapet	23.20	10.25	11.05	OL	Insulator Replacement Near at Mominapur	Maddur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 21.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole	Bheemaram	11KV	Nalgonda	13.15	14.55	01.40	E/L	11KV Jumper Cut	-
2		Telekantigudem	Telekantigudem	11KV	Nalgonda	14.10	14.50	00.40	E/L	11KV Jumper Cut	-
3		Eduloor	Naregudem	11KV	Nalgonda	12.30	15.30	03.00	E/L	11KV Jumper Cut	-
4		Ravulapally	Ravulapally	11KV	Suryapet	04.40	07.30	02.50	E/L	11KV Jumper Cut	-
5		Mamillagudem	Mamillagudem	11KV	Huzurnagar	14.10	15.30	01.20	E/L	11KV Line Snapped	-
6		MR.Gudem	Gangasanpally	11KV	Bhongir	12.40	13.40	01.00	EL/OL	11kv Insulato Failed near Rambavi	-
7		NG.Bandal	Gandamalla	11KV	Bhongir	08.00	09.53	01.53	EL/OL	11kv line snapped at SS-1 near Gandamalla (V)	-
1	SDPT	Pullur	Pullur	11KV	Siddipet	09.40	10.05	00.25		B/D for Insulator fail	-
2		Raghvapur	Peddalingareddypally	11KV	Siddipet	11.30	15.30	04.00		B/D for Heavy gali	
3		Raghvapur	Raorukula	11KV	Siddipet	12.15	16.30	04.15		B/D for HT/LT Line phase to phase	
4		Laxmidevipally	Laxmidevipally	11KV	Siddipet	12.20	13.40	01.20		B/D for Tree branches fall on 11KV line	
5		Chatlapally SS	Anthaiguda Feeder	11KV	Gajwel	11.35	12.15	00.40		Jumper Cut	
6		Ahmedipur SS	Kolgur Feeder LC 27478	11KV	Gajwel	14.10	14.50	00.40		Phase to Phase Falt	
7		Thunki Bollaram SS	Achaipally LC 19961	11KV	Gajwel	4;50	11.45	05.55		11KV Wire Cutting	
8		Duddeda SS	Selampur AGL LC 21249	11KV	Gajwel	14.20	16.00	01.40		Problem not Found	
9		Marpadaga SS	Khammampally AGL LC 28116	11KV	Gajwel	11.50	16.50	05.00		HT by LT Touching	
10		Marpadaga SS	Nagireddypally LC 28118	11KV	Gajwel	17.30	18.35	01.00		Disk Fail	
11		Mubaraspur SS	thirmalapur Feeder LC 11671	11KV	Gajwel	13.45	17.05	03.25		HT by LT touching	
12		dommata SS	Surampally Feeder LC 12099	11KV	Gajwel	13.25	15.05	00.40		AB Switch Problem	
13		Raipole SS	Chouder pally LC 10953	11KV	Gajwel	16:53	18:50	02:03		11 KV Line wire Cutting	
14		Gudikandula SS	Gudikandula 24 hrs Feeder LC 14124	11KV	Gajwel	11.05	12.06	01.01		11 KV Wire cutting	-
15		Rampur SS	Rampur Feeder	11KV	Gajwel	11.45	12.55	01.10		Problem not Found	-
16		Bejjanki	Cotton mill	11KV	Husnabad	12.00	17.00	05.00		Line cutting	-
17		Thotapally	Thotapally rural	11KV	Husnabad	11.20	16.20	05.00		Haevy gale and wind (3-Ph)	-
18		Regulapally	Mallamchervu	11KV	Husnabad	17.20	19.25	02.05		Line cutting	-

1	RR N	Kolthur	Kolthur	11KV	Medchal	11.30	12.10	00.40	BD	Tree branch fallen on the 11KV Line at Wines, Thurkapally Road	-
2		Laxmapur	Laxmapur	11KV	Medchal	13.30	14.10	00.40	BD	11KV Pin Insulator failed at Balesh Bhavi, Laxmapur	-
1	RR E	CRPF	Chennapur	11KV	Keesara	13.05	13.20	00.15		LINE AB swicth open at malkaram no falt found	-
2		CRPF	Chennapur	11KV	Keesara	14.05	14.35	00.30		LINE AB swicth open at malkaram no falt found	-
1	HYD N	Seethaphal Mandi	Namala Gundu	11KV	Sec-Bad	07.25	09.10	01.45	EL,OL	O/G Cable fault at Road Crossing (2Nos. DTR's Kept off)	-
2		Srinagar Colony	Kamalapuri Colony	11KV	Banjarahills	14.01	15.13	01.12	AR tripped	No Visible Fault	-