

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044	2	3	2	3	2	3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>3</b>	<b>2</b>	<b>3</b>	<b>2</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>8</b>	<b>4</b>	<b>8</b>	<b>4</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 23.05.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Bijinepally	33KV	Nagarkurnool	08.33	09.38	01.05	EL	No Visible fault	Bijinepally	-
2		Alwal	Water Gridd	33KV	Shadnagar	13.00	17.46	04.46	EL	Insulator failed	Water Gridd	-
1	HYD N	132KV Erragadda	S.P.R.Hills	33KV	Allwyn	08.34	08.43	00.09	EL,OL-Yph	Cable fault	S.P.R.Hills	Loads transferred onto 132KV J' Hills - Yousufguda
1	HYD S	220KV Ch' Gutta - Santosh Nagar OH	Arundathi Colony	33KV	Malakpet	16.25	16.35	00.10	EL,OL-R&Bph	DRDL Arundathi Colony Partial bit Cable problem	Arundathi Colony	Loads transferred onto 220KV Ch' Gutta - C.R.P.F

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 23.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gangapur	Alwanpally	11KV	Mahabubnagar	07.10	08.10	01.00		B.D.11Kv wire Cut Near Gangapur (Vi).	-
1	NLG	Choutuppal	Jublakpally	11KV	Choutuppal	08.35	09.05	00.40	EL	63kv DTR Failed near Dharmoji Gudem	-
1	SDP	Jagdevpur	Jagadevpur SS	11KV	Gajwel	08.35	09.50	01.15		Cunductor Snapped	-
2		Ankshapur	Nagarajupally	11KV	Siddipet	08:05	11:34	03:29		Break down Line snapped	-
3		Chellapur	Godugumarri	11KV	Siddipet	08:50	13:54	05:04		B/D Line cut	-
1	HYD N	Marredpally	R.K Puram	11KV	C-VI	15.50	19.25	03.35	EL,OL-Rph	2no. Poles damaged due to Vechile dash at AOC Gate	16:30Hrs Partial feeder charged OK
2		Jubilee Hills	Jubilee Hills	11KV	X	21.45	22.47	01.02	EL,OL	Relay fault at SS	Arranged B/F on 11KV UCO Bank for
1	HYD S	Moosarambagh	Dilsukh Nagar	11KV	VIII	03.15	04.32	01.17	EL,OL	Cable End Kit failed at ICON Hospital	-