

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	2		2		2				
	Total	606	3055	2	1	2	1	2	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		2		2		2			
3	MDK	107	933	2		2			2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	2	4	2	2	4	0	0	
	Grand Total	1082	6468	6	3	6	3	4	5	0	0	

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Mahabubnagar	21.15	23.20	02.05	E/L	Line Isolator Opened at gudeballore (vi) (Krishna , Tangidi Dark) 33KV Pole Damaged near Kaustubha hostel		No
2		Balanagar	Surya Jyothi(MYK)	33KV	Jadcherla	17.30	22.40	05.10	E/L	for Tree Fallen on the Line Near Balanagar Police station		No
1	MDK	R.C.Puram	JK Fenner	33KV	Patancheru	19.25	21.40	02.15		B/D due to Pin Insulator failure		-
2		Borpatla	Waddepally	33KV	Jogipet	16.25	19.25	03.00		B/D due to Pin Insulator failure & Jumpercut		-
1	HYD N	132KV J' Hills	Devabhoomi - 2	NT	Kalyan Ngr	16.05	16.25	00.20	OL-Bph	Under Breakdown	Loads transferred onto 132KV J' Hills SS via 33KV Devabhoomi-4	-
1	HYD S	220KV Ch' Gutta	Malakpet Gunj	ST	Malakpet	16.10	16.17	00.07	EL	Under Breakdown	Loads transferred onto 132KV Imlibun SS	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 26.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Jalalpuram	Jalalpuram	11KV	Suryapet	07.30	10.55	03.25	EL	Insulator failed	-
2		Ambala	Ambala	11KV	Bhongir	07.15	08.20	01.05	OL	11 kv Insulator failed near Sub station 3 rd pole	-
1	RR N	Kolthur	Kolthur	11KV	Medchal	15.00	18.50	03.50		11KV Disc Failed and replaced at Bagireddy Thota,Kolthur	-