

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	2	1	2	1	2	1			
	Total	606	3055	2	3	2	3	2	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	10	1	10	1	10	1			
2	NLG	144	988	1	10	1	10	1	10			
3	MDK	107	933		1		1		1			
4	SDPT			3	15	3	15	3	15			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	14	27	14	27	14	27	0	0	
	Grand Total	1082	6468	16	30	16	30	16	30	0	0	

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Manthathi	33KV	Nagarkurnool	03.40	03.55	00.15	O/L	No Visible Fault	Manthathi	-
2		Makthal	Narwa	33KV	Narayanapet	05.05	12.10	07.05	E/L&O/L	Squarrel & Tree branch fallen on the line and removed Near Golapally	Narwa	-
3		Makthal	Paspula	33KV	Narayanapet	05.10	06.40	01.30	E/L	No Visible Fault	Paspula	Isolator open at Paspula SS
4		Maddur	Kankurthy	33KV	Narayanapet	07.30	08.05	00.35	E/L	Conductor snapped	Kankurthy	Alternate Supply Arranged form Mogalmdaka SS
5		Marikal	Ekilapur	33KV	Narayanapet	05.12	09.05	03.53	E/L	Pin Binding Failed at Jinnaram Gate	Ekilapur	-
6		Thirumalaipally	Madanapur	33KV	Wanaparthy	02.50	03.30	00.40	E/L	Tree fallen on the line at Tipadam pally	Madanapur	-
7		Amarchinta	Chandra Gattu Lift	33KV	Wanaparthy	11.06	12.59	01.53	E/L	LA Problem at Amarchintha SS	Chandra Gattu Lift	-
8		Gadwal	Oil Seeds	33KV	Gadwal	07.25	11.30	04.05	E/L	V Crassaram Damaged & Top Insulator & Line twisted near ADE/OP/Gadwal Office	Oil Seeds	Alternenate Supply Taken From Jallapur at 11:30Hrs.
9		Gadwal	Maldakal	33KV	Gadwal	06.25	09.05	02.40	E/L	Mallemdoddi Jumper open at Maldakla	Maldakal	-
10		Sri Rangapur	Chouder Gudem	33KV	Shadnagar	00.30	07.05	06.35	E/L	Disc Failed near Scan Company	Chouder Gudem	-
1	NLG	Bibinagar	Venkireyala	33KV	Bhongiri	21.07	06.35	09.28	EL/OL	3 NO's 33 kv Disc failed at Bharath Gas Godam near Bibinagar town	Venkireyala	-
1	SDP	Shanigaram	Koheda	33KV	Husnabad	03.50	12.45	08.55		BD Pin binding failure at Kurella (V)	Koheda	-
2		Shanigaram	Begumpet	33KV	Husnabad	04.10	10.25	06.15		BD Insulater Y Phase Failure	Begumpet	-
3		Thukkapur	Mirdoddy	33KV	Gajwel	00.05	08.20	08.15		Jumper cut	Mirdoddy	-
1	HYD S	220KV Osm.University	I.I.C.T	33KV	Chilalguda	00.05	00.15	00.10	OL-Bph	Cable fault	I.I.C.T	Loads transferred onto 220KV Moulali SS via 33KV Azamabad SS
2		220KV Shi.Pally	Miralam	33KV	Malakpet	04.00	04.08	00.08	EL,OL-Bph	Cable fault	Miralam	Loads normalised to 33KV Shi.Pally - Ch' Baradari OH line

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.05.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Karvena	11KV	Jadcherla	05.30	11.00	05.30		11 KV Insulator fail near karchalabanda thanda	-
1	NLG	Koduru	Kommala	11KV	Suryapet	01.30	05.20	03.50	E/L	Insulaotr flashover	-
2		B.Chandupatla	V.K Pahad	11KV	Suryapet	02.10	05.00	02.50	E/L	Toddy tree branch fallen	-
3		Thungathurthy	Ganugubanda	11KV	Suryapet	05.30	08.35	03.05	E/L	Insulaotr flashover	-
4		Raghunadapalem	Nakkalagudem	11KV	Huzurnagar	10.00	13.00	03.00	EL	Due to 11lv Jumper cutted	-
5		Pottichelama	Ramannagudem	11KV	Miryalaguda	04.30	06.00	01.30	EL	11KV Jumper Cut	-
6		Venkatapur	Venkatapur	11KV	Bhongir	00.00	09.45	09.45	EL/OL	11 kv Line snapped near Venkatapur village	-
7		Bibinagar	Arunteja	11KV	Bhongir	00.00	07.20	07.20	EL/OL	11 kv Pin Insulator failed at Hindusthan godam Near Bibinagar town	-
8		Alair	Ch.Kandukur	11KV	Bhongir	08.30	11.30	03.00	EL/OL	11kv Insulator Failed near Ch.Kandukur Village	-
9		Golankonda	Golankonda	11KV	Bhongir	05.00	12.05	07.05	EL/OL	2no 11kv Insulators Failed & 11kv Line sanpped near Ammanabolu Village	-
10		Velmajala	Seetharampur	11KV	Bhongir	06.45	12.35	05.50	EL/OL	SS-86 25kv DTR Failed	-
1	MDK	Patancheru	Inole	11KV	Sathyasai WW	08.45	10.05	01.20		BD Due to HT / LT Jumpercut	-
1	SDP	Akkannapet	Pakilnayak Thanda	11KV	Husnabad	05.53	07.10	01.17		11KV line cut	-
2		Gouravelly	Gouravelly Rural	11KV	Husnabad	04.45	05.50	01.05		DTR Failure	-
3		Bejjanki	Muthannapet	11KV	Husnabad	02.00	06.00	04.00		Tree fallen on Conductor	-
4		Ramchandrapur	Vinjapally	11KV	Husnabad	03.00	05.55	02.55		Tree fallen on Conductor	-
5		Ramchandrapur	Varikolu	11KV	Husnabad	02.50	05.55	03.05		Tree fallen on Conductor	-
6		Koheda	Venkateshwarapally	11KV	Husnabad	12.50	14.00	01.10		Insulator Failure	-
7		Komuravelly	Komuravelly Agl	11KV	Husnabad	09.50	15.10	05.20		11KV line cut	-
8		Chityal	Chityal Agl	11KV	Husnabad	04.30	05.20	00.50		Tree fallen on Conductor	-
9		Chityal	Dommeta	11KV	Husnabad	04.30	11.20	06.50		Tree fallen on Conductor	-
10		Gagillapur	Gagillapur Agl	11KV	Husnabad	07.00	07.23	00.23		Tree fallen on Conductor	-
11		ERRAVALLY	ERRAVALLY	11KV	Gajwel	09.26	11.47	02.21		Insulater barning	-
12		MULUGU	MULUGU	11KV	Gajwel	10.20	12.22	02.05		11 KV line cut	-
13		Komaticheruvu	Srinagar colony	11KV	Siddipet	04.30	05.34	01.04		B/D-Tree bunches fallen on 11KV line	-
14		Nangnoor	Akkanapally	11KV	Siddipet	05.35	10.30	04.55		B/D-11KV pininsulator fail-B/D rectified	-
15		Kammarlapally	Kothapally	11KV	Siddipet	03.47	08.30	04.43		B/D-tree bunches fallen on 11KV line-B/D rectified	-
1	RR N	Kolthur	Anantaram	11KV	Medchal	07.45	08.30	00.45	BD	Bird fallen on 11KV Line at Balaraju bavi,Anatharam Road	-
1	RR E	Uppal	Ghatkesar	11KV	Habsiguda	21.20	21.50	00.30		11KV HG Fuse set blast & fallen on HT Jumper at Beerappa Gadda Smasana Vatika	-
1	HYD C	Nampally	Badi Masjid	11KV	VII	13.58	15.15	01.17	W/O Indication	Erected Pole & strung Line at Bazarghat X Road	-