

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	9	0	9	0	9	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Vitlapur(Mushrifa)	11KV	Narayanapet	05.05	08.00	02.55		HT Line conductor fallan on LT	-
1	NLG	Nuthankal	Chilpakuntla	11KV	Suryapet	06.50	08.10	01.20	E/L	Bird fallen on the line	-
2		Munagala	Kokkereni-2	11KV	Huzurnagar	06.10	08.40	02.30	EL	11 KV LINE SNAPPED	-
3		Kethepally	Inupamula	11KV	Nalgonda	02.25	07.50	05.25	EL	AB switch problem at Jamail thota	-
4		Palem	Ogodu	11KV	Nalgonda	10.55	14.35	03.40	EL	11KV jumper cut	-
5		Koppol	Bheemaram	11KV	Nalgonda	13.35	15.30	01.55	EL	11KV jumper cut	-
1	RR N	Aliabad	HBL	11KV	Medchal	12.25	13.40	01.15	BD	Tree fallen on the 11KV Line at HBL Colony	-
1	HYD N	Zamistanpur	Sanjeevapuram	11KV	V	03.16	04.26	01.10	EL,OL-Yph	4No. DTR's fault at S.R.Hospital	-
2		Chilkaiguda	New Boiguda	11KV	V	11.48	13.32	01.44	EL,OL-Bph	Tree branches fallen on lines at Krishna Nagar & O/G AB Switch male & female contact problem at SS	-