

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	10	0	10	0	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD N				NIL							-
8	HYD S				NIL							-
9	HYD C				NIL							-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 04.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Nancherla	Komreddypally	11KV	Narayanapet	09.12	11.04	01.52		SQUIRREL FALLEN ON THE LINE, ANNSAGAR AGL SIDE	-
2		MOGALMADKA	ANNASAGAR	11KV	Narayanapet	09.19	11.08	01.49		11KV Insulator failed	-
1	NLG	Akaram	Vaddipamula	11KV	Nalgonda	10.00	14.30	04.30	EL	11KV Insulator failed	-
2		Gaddipally	Gaddipally	11KV	Huzurnagar	06.15	08.00	01.45	EL	11 KV LINE SNAPPED	-
1	SDPT	Chityala	Thadur	11KV	Husnabad	01.05	11.05	10.00		Jumper Out	-
2		NACHARAM	NARSAMPALLY	11KV	Gajwel	14.10	16.50	02.40		BREAKDOWN & Autometrically Stand	-
3		GOWRARAM	MAILARAM	11KV	Gajwel	15.00	16.00	01.00		3-Ph BREAKDOWN (1-Ph RUNNING)	-
4		MD SHAPUR	LINGAIPLAAY THANDA	11KV	Gajwel	01.05	11.50	11.45		BREAKDOWN (11KVA LINE CUT)	-
1	RR N	Subhash Nagar	Ramaraj Nagar	11KV	Medchal	13.05	14.20	01.15	EL	Tree Branch fallen on the 11KV Line at Green Park	-
2		Maytas	Apartment	11KV	Kukatpally	17.01	18.05	01.04	EL	Apartment Breakar prblem	-