

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 05.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD N				NIL							-
8	HYD S				NIL							-
9	HYD C				NIL							-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 05.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Pittampally	11KV	Nalgonda	01.00	07.28	06.28	E/L	Tree branches touches to 11KV line	-
2		Rajapeta	Renukunta Agl	11KV	Bhongir	05.00	10.00	05.00	EL/OL	11Kv Insulator failed at Jitta .Harinathreddy well near Renikunta (V).	-
1	SDPT	Vantimamidi SS	Chinnathimmapur Feeder	11KV	Gajwel	13.30	14.45	01.15		Jumper cut	-
2		Kokkonda SS	Nuzivedu Feeder	11KV	Gajwel	17.05	18.05	01.00		Jumper cut	-
3		Maddur	Ladnoor AGL	11KV	Husnabad	03.55	09.20	05.25		11 kv line Fallen	-
1	RR S	Kothaguda	lzzathnagar	11KV	Kondapur	13.48	14.58	01.10		11kv AB Cable failed near Alekhya homes at lzzathnagar	-
1	HYD N	Srinagar Colony	Kamma Sangam	11KV	Banjarahills	12.56	14.59	02.03	EL,OL-Yph	No Visible Fault	-
1	HYD C	Golconda	Brindavan Colony	11KV	Mehdipatanam	01.00	02.04	01.04	EL	Cable fault	Arranged B/F on 11KV Hakimsha fdr